



CITROËN BERLINGO: FJ-335-FG

Vinnumber:	VR7EFBHYBKN528643	Versionname:	CITROËN BERLINGO M 1000kg BlueHDi 100 S&S
First Registrationdate:	30/07/2019		BVM Worker VU [4P] bvm 5-100CH-5cv
Expertise Mileage:	147781		(fourgonnettesimple cabine)
Bodytype:	Transporter	Fiscalpower:	73
Gearbox:	MAN 5 VIT	Power Kw:	White
Transmission:	Front	Body colour:	Opaque
Fueltype:	Diesel	Paint type:	Black
Engine functioning:	Yes	Interior colour:	Steel
Battery functioning:	Yes	Type of rims (mounted):	Black
Vehicle running:	Yes	Dashboard color:	
Number of doors:	4		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	VS		

Options

Number of keys total	2	Radio	
Number keys remote	1	Sliding door right-side	
Windows electric F		Seat cover lining	Lining Other
Cruise Control			
Type of climate control	Manual climate control		

Tyres

195/65/15/91 H			
Summer tyres:	Fr.L.	Firestone: 55%	Fr.R.
	Re.L.	Hankook: 40%	Re.R.
		Firestone: 55%	Hankook: 40%
Tyre profile depth FL			4.5
Tyre profile depth FR			4.7
Tyre profile depth RL			5.6
Tyre profile depth RR			5.5
Tyre size FL			195/65 R 15 91 H
Tyre size FR			195/65 R 15 91 H
Tyre size RL			195/65 R 15 91 H
Tyre size RR			195/65 R 15 91 H
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			258
Tyre make FR			258
Tyre make RL			260
Tyre make RR			260

Assistance equipment

Spare wheel	Yes	Jack	Yes
Outer sill L, Dent(s) and scratch(es), Replace and paint			



Door FL, Scratch(es), Paint



Bumper F, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Sliding door R, Scratch(es), Paint



Side wall RR, Dent(s), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Historique Maintenance

Immatriculation: FJ-335-FG Date de 1ère immatriculation: 30/07/2019

Modèle: Citroen BERLINGO M 1000kg BlueHDi 100 S&S BVM Worker VU [4P] bvm 5-100CH-5cv (fourgonnettesimple cabine)

Date	Kilométrage	Fournisseur	Descriptif
16/04/2026	146.893	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
	0		PERMUTATIONS PNEUS
	0		PERMUTATIONS PNEUS
	0		REPLACEMENT PNEUS ETE
29/12/2025	139.123	GARAGE SATHONAY	PLAQUETTES AV RPLT
	0		LIQUIDE DE FREIN
	0		REVISION ET CLIM
	0		JANTE RPLT
	0		TRIANGLE INFERIEUR AVG RPLT
	0		TRIANGLE INFERIEUR AVD RPLT
	0		ADBLUE
	0		BALAIS ESSUIE GLACE AV
	0		ECLAIRAGE DE PLAQUE RPLT
19/11/2025	136.215	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS HIVER
17/06/2025	125.687	CENTRE DE CONTROLE TECHNIQUE AUTOMOBILE DE CORBAS	CONTROLE TECHNIQUE
10/03/2025	118.062	GARAGE SATHONAY	DIAG
	0		LAMPE CODE AVD RPLT
	0		LAMPE AR RPLT
	0		ECLAIRAGE DE PLAQUE RPLT
	0		CARDAN AVG RPLT
	0		AMORTISSEURS AV RPLT
14/01/2025	112.304	MS AUTOMOBILES	SONDE LAMBDA RPLT
13/12/2024	112.203	MS AUTOMOBILES	PLAQUETTES AV RPLT
	0		POT CATALYTIQUE FAP RPLT
	0		REVISION
	0		DIVERS CLIM
	0		DIVERS ECHAPPEMENT
	0		BALAIS ESSUIE GLACE AV
	0		PLAQUETTES AR RPLT
20/09/2024	106.566	GARAGE SATHONAY	NEIMAN RPLT
	0		TELECHARGEMENT CALCULATEUR

Historique Maintenance

Immatriculation: **FJ-335-FG**

Date de 1ère immatriculation: **30/07/2019**

Modèle: **Citroen BERLINGO M 1000kg BlueHDi 100 S&S BVM Worker VU [4P] bvm 5-100CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
26/06/2024	100.874	CENTRE DE CONTROLE TECHNIQUE AUTOMOBILE DE CORBAS	ANTIPOLLUTION
12/06/2024	99.609	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
28/12/2023	85.800	GARAGE SATHONAY	ADBLUE
	0		LIQUIDE DE FREIN
	0		REVISION ET CLIM
	0		DISQUES PLAQUETTES AV RPLT
	0		HUILE BV RPLT
	0		SOUFFLET DE CARDAN RPLT
	0		BALAIS ESSUIE GLACE AV
07/12/2023	85.184	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS HIVER
27/10/2023	83.073	GARAGE SATHONAY	LIQUIDE LAVE GLACE
	0		LAMPE CODE AVD RPLT
27/06/2023	74.186	CENTRE DE CONTROLE TECHNIQUE AUTOMOBILE DE CORBAS	CONTROLE TECHNIQUE
13/06/2023	72.983	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
02/05/2023	70.318	GARAGE SATHONAY	LAMPE RPLT
27/12/2022	61.992	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
19/12/2022	61.647	GARAGE SATHONAY	REVISION ET CLIM
	0		ADBLUE
	0		BALAIS ESSUIE GLACE AV
04/05/2022	46.779	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
27/12/2021	36.858	GARAGE SATHONAY	LIQUIDE DE FREIN
	0		PLAQUETTES AV RPLT
	0		ADBLUE
	0		BALAIS ESSUIE GLACE AV
	0		REVISION ET CLIM ET AIR ET CARBURANT
10/12/2021	36.251	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS HIVER
13/04/2021	21.962	EUROFLEET TYRES AND SERVICES	REPARATION DE ROUE
30/12/2020	15.697	GARAGE SATHONAY	ADBLUE
	0		REVISION

Historique Maintenance

Immatriculation: **FJ-335-FG**

Date de 1ère immatriculation: **30/07/2019**

Modèle: **Citroen BERLINGO M 1000kg BlueHDi 100 S&S BVM Worker VU [4P] bvm 5-100CH-5cv
(fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
	0		BALAIS ESSUIE GLACE AV