



RENAULT EXPRESS: 9943-MCF

Vinnumber:	VF1RJK00970098888	Versionname:	Confort 1.5 Blue dCi 70 kW (95 cv) furgón derivado de turismo 70kW 4P manual
First Registrationdate:	14/11/2022	Fiscalpower:	
Expertise Mileage:	76254	Power Kw:	
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Radio:	
Number keys remote:	2		
Windows electric F:			
Cruise Control:			
Steering wheel multifunctional:			
Type of climate control:	Manual climate control		

Tyres

185/65/15/88 T				
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				185/65 R 15 88 T
Tyre size FR				185/65 R 15 88 T
Tyre size RL				185/65 R 15 88 T
Tyre size RR				185/65 R 15 88 T
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
--------------	------------	-------	------------

User's manual, Missing, Repair/replace (lump sum)



Dashboard, Scratch(es), Replace



Boot lid covering R, Broken, Replace



Boot lid covering R, Broken, Replace



Door panel RR, Broken, Replace



Door panel FR, Scratch(es), Replace



Door FL, Scratch(es), Paint



Wing FL, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Paint



Door trim FR, Deformed / Strained, Replace



Door FR, Scratch(es), Paint



Sliding door R, Scratch(es), Paint



Door trim RR, Scratch(es), Repair and paint (complete)



Side wall RR, Dent(s), Repair and paint (complete)



Bumper R, Scratch(es), Paint



Boot door panel RR, Dent(s), Repair and paint (complete)



Boot door panel RL, Dent(s), Repair and paint (complete)



Tyres, No damage, Check

