

INSPECTION REPORT

End of contract

GENERAL INFO

File	315832
License plate	2BMQ164
Vehicle identification number	WBY7X41010S157099
Dossier	2021 090 159
Make	BMW iX3 sDrive35
Mileage	137383
First registration	17/01/2022
client availability date	26/06/2026
inspectionDate	16/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
41	Windshield // Replace	Y
66	Wing Front Left // Polish	Y
106	Door Rear Left // Polish	Y
116	Wing Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
184	Wing Rear Right // Repair & Painting	N
191	Door Rear Right // Smart Repair Medium	N

Damage Pictures



Bumper Front // Smart Repair Large-scratch



Bumper Rear // Polish-scratch



Wing Rear Left // Polish-scratch




Door Rear Left // Polish-scratch



Wing Front Left // Polish-scratch



Wing Rear Right // Repair & Painting-scratch + dent



Door Rear Right // Smart Repair Medium-scratch + dent



Windshield // Replace-cracked