

## MERCEDES

Vehicle reference:

**W1VVMLFZ9S4408759**

Engine size:

1950 cm<sup>3</sup>

Number of doors:

5

Combustion engine power:

140 kW / 190 hp


Fuel type:

Diesel

## Quick Check

### Damage

This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.

 **Damage**

### Import

No data available

 **No data available**

Located in Italy



# Damage Overview

11/2025 Damage reported



**Affected area:**

Not available

**Reported on:**

11/2025

**Severity scale:**


Minor

**Reported in:**

Italy

**Damage type/cause:**

Not available



## Damage Glossary

### Damage

Damage refers to any harm or impairment to a vehicle's physical components, affecting its appearance, functionality, or safety. Damage can range from cosmetic issues like scratches and dents to severe structural problems. It can be caused by collisions, weather events, vandalism, or other incidents.

# Owners BETA

**i** No owners found: No owners found

# History information

Date

Event

11/2025

Damage reported in Italy

For this Vehicle History Report, we searched over 40 billion records from more than 30 European countries, the USA, and Canada.

## Technical details

### Engine and performance

|                         |                        |
|-------------------------|------------------------|
| Fuel type               | <b>Diesel</b>          |
| Combustion engine power | <b>140 kW / 190 hp</b> |

### Other information

|                 |          |
|-----------------|----------|
| Number of doors | <b>5</b> |
|-----------------|----------|

# CARFAX Glossary

## Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

## Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

## Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

## Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

## Severity scale - Severe

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

## Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

# How to use this report



This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time. Read more in our [Terms and conditions](#).