

## 2006 MERCEDES AMG GT 63 S 4MATIC+

Vehicle reference:

**WDD2906891A014275**

Engine size:

3982 cm<sup>3</sup>

Fuel type:

Petrol

Combustion engine power:

470 kW / 639 hp

Drive:

AWD

Gearbox type:

Automatic

Number of doors:

4

## Quick check


### **Damage**


This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.


### **Import**


Not a private import

## Legend

 No issues reported or indicated

 Valuable Information

 Requires attention


 Data unavailable

# Damage overview

10/2021

## Affected area (6):

Location reference, does not indicate the extent of the damage.



Reported in  
Italy

Damage type/cause  
Collision with another vehicle

## Damage severity:




Minor to Moderate

Mostly cosmetic damage, such as dents or scratches. Some components may have additional damage, but vehicle operation and safety are generally not impacted.

02/2022

## Affected area (3):

Location reference, does not indicate the extent of the damage.



Reported in  
Italy

Damage type/cause  
Vandalism

## Damage severity:




Minor

Cosmetic damage only, including small dents or scratches that may need touch-ups. Does not affect vehicle operation or safety.

06/2022

**Affected area (1):**

Location reference, does not indicate the extent of the damage.



**Reported in**  
Italy

**Damage type/cause**  
Not available

**Damage severity:**




Minor

Cosmetic damage only, including small dents or scratches that may need touch-ups. Does not affect vehicle operation or safety.

07/2024

**Affected area (1):**

Location reference, does not indicate the extent of the damage.



**Reported in**  
Italy

**Damage type/cause**  
Not available

**Damage severity:**



Minor

Cosmetic damage only, including small dents or scratches that may need touch-ups. Does not affect vehicle operation or safety.

**Damage Glossary**

**Damage**

Damage refers to any harm or impairment to a vehicle's physical components, affecting its appearance, functionality, or safety. Damage can range from cosmetic issues like scratches and dents to severe structural problems. It can be caused by collisions, weather events, vandalism, or other incidents.

 **CARFAX tips**



Keep in mind: while our data shows no further damage, additional events may have occurred. CARFAX only reflects information that's been reported to us.

It's still important to take a close look at the vehicle during your test-drive. Small details can sometimes hint at past repairs. Keep an eye out for paint inconsistencies or uneven panels.

## Owners BETA



### Owner(s) in Italy

Purchase year: **2020**

Damage reported on: **07/2024 , 06/2022 , 02/2022 , 10/2021**

# Technical details

## Engine and performance

**Fuel type**  
Petrol

**Combustion engine power**  
470 kW / 639 hp

## Other information

**European vehicle category**  
M1

**Number of doors**  
4

# History information

Date	Mileage	Event
2020-01-03		<b>Registered in Italy</b>
10/2021		<b>Damage reported in Italy</b>
02/2022		<b>Damage reported in Italy caused by vandalism</b>
06/2022		<b>Damage reported in Italy</b>
07/2024		<b>Damage reported in Italy</b>

For this Vehicle History Report, we searched over 40 billion records from more than 30 European countries, the USA, and Canada.

# Carfax glossary

## **Model year**

This term is defined by the manufacturer but it is typically the year the vehicle is built. If the model year does not appear on the CARFAX report, it is because the manufacturer did not include this information in the VIN. Model year can normally be determined by the vehicle age.

## **Number of records**

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

## **Quick check**

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

## **Severity scale - Minor**

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

## **Severity scale - Moderate**

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

## **Severity scale - Severe**

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

## **Vehicle reference**

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

## How to use this report



This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time. Read more in our [Terms and conditions](#).