



Volkswagen Passat:			
Vinnumber:	WVWZZZ3CZNE073260	Versionname:	
First Registrationdate:	30/05/2022	Fiscalpower:	
Expertise Mileage:	149339	Power Kw:	115
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2825
Fueltype:	Hybrid Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options			
Number of keys total	2	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	Tow bar collapsible
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres


215/55/17/92 H				
Summer tyres:	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/55 R 17 92 H
Tyre size FR				215/55 R 17 92 H
Tyre size RL				215/55 R 17 92 H
Tyre size RR				215/55 R 17 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Number of charging cables (normal)	0	
Number of charging cables (rapid charge)	1	
Total cost ex VAT		77,26
Seat cover FL, Damaged, Acceptable		0,00



Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------



Alloy rim RL, Scratch(es), Acceptable	0,00
---------------------------------------	------



Wing FL, Dent(s), Acceptable	0,00
------------------------------	------



Charging cable (normal), Missing, Check	0,00
---	------



Bumper R, Bad repair, Check	0,00
-----------------------------	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Rear window, Scratch(es), Polish	77,26
----------------------------------	-------



Wing RR, Dent(s), Acceptable	0,00
------------------------------	------



Roof, Dent(s), Acceptable	0,00
---------------------------	------

