



RENAULT CLIO: GJ-033-SB

Vinnumber:	VF1RJA00769640526	Versionname:	RENAULT CLIO Business E-Tech hybride 140 -21N
First Registrationdate:	28/09/2022	Fiscalpower:	VP [5P] bva 6-140CH-5cv (bi-corps)
Expertise Mileage:	149243	Power Kw:	103
Bodytype:	Berline	Body colour:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Hybrid	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Seat cover lining	Lining Other
Steering wheel leather			
Type of climate control	Manual climate control		

Tyres

195/55/16/97 V				
Summer tyres:	Fr.L.	Hankook: 80%	Fr.R.	Hankook: 85%
	Re.L.	Hankook: 55%	Re.R.	Hankook: 55%
Tyre profile depth FL				2.7
Tyre profile depth FR				2.4
Tyre profile depth RL				4.5
Tyre profile depth RR				4.6
Tyre size FL				195/55 R 16 97 V
Tyre size FR				195/55 R 16 97 V
Tyre size RL				195/55 R 16 97 V
Tyre size RR				195/55 R 16 97 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Interior, Stain, Cleaning



Wheel cover FR, Missing, Replace



Wheel cover FL, Missing, Replace



Tyre FL, Out of tolerance, Replace



Tyre FR, Out of tolerance, Replace



Wing FL, Scratch(es), Paint



Door FL, Scratch(es), Paint



Outer door handle FL, Incomplete, Replace



Door RL, Scratch(es), Paint



Wing RL, Scratch(es), Polish



Grille, Unclassped, Dismount/Mount



Headlight R, Scratch(es), Replace



Bumper F, Scratch(es), Repair and paint (complete)



Bumper moulding FR, Unclassped, Dismount/Mount



Wing RR, Scratch(es), Polish



Door FR, Dent(s), Repair and paint (complete)



Bumper R, Deformed / Strained, Replace and paint



Bodywork, Not original part, Sticker removal small



Historique Maintenance

Immatriculation: **GJ-033-SB** Date de 1ère immatriculation: **28/09/2022**

Modèle: **Renault CLIO Business E-Tech hybride 140 -21N VP [5P] bva 6-140CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
09/05/2025	110.283	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
18/03/2025	106.740	ESPACE AUTOMOBILE D'AUVERGNE	JAUGE A CARBURANT RPLT
06/03/2025	102.030	ESPACE AUTOMOBILE D'AUVERGNE	DIAG
	0		DIVERS ELEC
	0		RETROVISEUR G RPLT
	0		RECYCLAGE
03/12/2024	96.513	ESPACE AUTOMOBILE D'AUVERGNE	BALAI ESSUIE GLACE AV
	0		RECYCLAGE
	0		REVISION ET CLIM
16/04/2024	64.871	ALLIANCE AUTOS	DIVERS
12/04/2024	64.278	AUTOS DIFFUSION SAINT ETIENNE	BALAI ESSUIE GLACE AR
	0		REVISION
	0		DISQUES PLAQUETTES AV RPLT
	0		BALAI ESSUIE GLACE AV
06/12/2023	45.720	EUROFLEET TYRES AND SERVICES	REFUS PNEU
	0		REPLACEMENT PNEUS HIVER
12/09/2023	33.144	ESPACE AUTOMOBILE D'AUVERGNE	REVISION ET CLIM
	0		RECYCLAGE
20/01/2023	3.248	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
19/01/2023	3.207	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS HIVER