MACADAM








PEUGEOT 3008: 7767-MFY

Vinnumber:	**VF3MCYHZUPS049748**	Versionname:	**1.5 BlueHDi 96kW S&S Allure Pack EAT8 todoterreno 96kW 5P automática**
First Registrationdate:	**31/03/2023**	Fiscalpower:	
Expertise Mileage:	**106455**	Power Kw:	
Bodytype:	**SUV**	Body colour	**Dark Blue**
Gearbox:	**Automatic**	Type of rims (mounted)	**Aluminium**
Transmission:			
Fueltype:	**Diesel**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Central consol F	
Number keys remote	**2**	Luggage cover	
GPS big screen color		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Radio multimedia			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**225/55/18/102 V**			
	Fr.L.	**Goodyear: 5 mm**	Fr.R.	**Goodyear: 5 mm**
	Re.L.	**Goodyear: 6 mm**	Re.R.	**Goodyear: 6 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**6.0**
Tyre profile depth RR	**6.0**
Tyre size FL	**225/55 R 18 102 V**
Tyre size FR	**225/55 R 18 102 V**
Tyre size RL	**225/55 R 18 102 V**
Tyre size RR	**225/55 R 18 102 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Repair kit	**Yes**

Boot lid covering R, Scratch(es), Replace




Wing trim FL, Scratch(es), Paint




Door RL, Scratch(es), Acceptable




Bumper F, Scratch(es), Repair and paint (complete)




Mirror side repeater R, Scratch(es), Replace




Door RR, Scratch(es), Repair and paint (complete)






Wing trim RR, Scratch(es), Acceptable




Internal boot lining R, Scratch(es), Acceptable




Internal boot lining L, Scratch(es), Replace




Tyres, No damage, Check



ALPHABET

Datos del vehículo

Marca	PEUGEOT	Matrícula	7767-MFY
Modelo	3008	VIN	VF3MCYHZUPS049748
Versión	1.5 BlueHDi 96kW S&S Allure Pack EAT8 todoterreno 96kW 5P automática		

Histórico

Fecha	Descripción	Kilómetros	Taller
29/04/2024	Rev. 30.000 kms	29000	AUTOS FERROL S.A.
25/09/2024	Sustitución	42362	ADAPTAMOVIL BERGONDO, S.L.
02/12/2024	Rev. 50.000 kms	50101	AUTOS FERROL S.A.
07/05/2025	Sustitución	65530	DEPOR CAR
26/05/2025	Aceite motor - - - ALP EURO, Arandela / tapón cárter - GOMA, Filtro aceite - bosch, Filtro aire-blue print, Filtro antipolen - MANN, Filtro combustible-blue print, Líquido lavaparabrisas - CONCENTRADO - Nueva, Serv inspección 60000 KM, Sustituir Filtro aire, Sustituir Filtro antipolen, Sustituir Filtro combustible, Tasa de gestión de aceites usados	67773	TALLERES MACEIRAS S.L.
14/01/2026	Alineado sencillo, Ecotasa - N2, Goodyear / 225/55R18 102V EFFICIENTGRIP 2 SUV XL, Sustitucion y kit de montaje	89474	NEUMATICOS DEPOR-CAR S.L.
06/04/2026	Aceite motor - - - ALP EURO, Arandela / tapón cárter - CAUTEX - Rec.Plat. EuroTaller - GOMA, Filtro aceite - bosch, Importe de pago por uso, Líquido lavaparabrisas - CONCENTRADO - Nueva, Serv inspección 90000 KM, Tasa de gestión de aceites usados	97253	TALLERES MACEIRAS S.L.

Fecha	Descripción	Kilómetros	Taller