



MERCEDES-BENZ GLC: GH-151-KN

Vinnumber:	W1N2539531G109365	Versionname:	MERCEDES-BENZ GLC 2.0 GLC 300 E BUSINESS LINE
First Registrationdate:	6/07/2022	Fiscalpower:	4MATIC VP [5P] bva 9-320CH-12cv (SUV)
Expertise Mileage:	38483	Power Kw:	235
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Beige
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Light Beige
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Panoramic roof	
GPS big screen color		Central consol F	
Windows electric F		Luggage cover	
Cruise Control		Headlights Xenon/LED/Laser	
Steering wheel multifunctional		Front parking sensors	
Steering wheel leather		Rear parking sensors	
Type of climate control	Autom climate control	Rear view camera	
		Seat cover lining	Lining Leather

Tyres

235/60/18/103 V				
Summer tyres:	Fr.L.	Bridgestone: 50%	Fr.R.	Bridgestone: 55%
	Re.L.	Bridgestone: 30%	Re.R.	Bridgestone: 35%
Tyre profile depth FL				5.0
Tyre profile depth FR				4.5
Tyre profile depth RL				6.1
Tyre profile depth RR				5.9
Tyre size FL				235/60 R 18 103 V
Tyre size FR				235/60 R 18 103 V
Tyre size RL				235/60 R 18 103 V
Tyre size RR				235/60 R 18 103 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)





Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing trim RL, Scratch(es), Replace



Bumper F, Scratch(es), Paint



Bumper moulding FR, Missing, Replace



Bumper spoiler F, Broken, Replace



Door FR, Scratch(es), Paint



Door RR, Scratch(es), Paint



Wing trim RR, Scratch(es), Replace




Wing RR, Scratch(es), Paint



Bumper moulding R, Deformed / Strained, Replace



Bumper spoiler Rear, Broken, Replace



Bumper R, Scratch(es), Paint



Historique Maintenance

Immatriculation: **GH-151-KN** Date de 1ère immatriculation: **06/07/2022**
Modèle: **Mercedes GLC 2.0 GLC 300 E BUSINESS LINE 4MATIC VP [5P] bva 9-320CH-12cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
08/07/2025	31.194	COMO WAGRAM	BALAIS ESSUIE GLACE AV
	0		REVISION
	0		LIQUIDE DE FREIN
24/06/2024	20.893	COMO WAGRAM	REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV
27/06/2023	8.127	COMO WAGRAM	REVISION
	0		BALAIS ESSUIE GLACE AV