



Peugeot 2008 (UKL): 2DMV152

Vinnumber:	VR3USHNSSNJ825609	Versionname:	2008 GT 1.2 Puretech S&S 130pk/cv 5p EAT8
First Registrationdate:	28/04/2023	Fiscalpower:	
Expertise Mileage:	14882	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

215/60/17/96 H				
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				215/60 R 17 96 H
Tyre size FR				215/60 R 17 96 H
Tyre size RL				215/60 R 17 96 H
Tyre size RR				215/60 R 17 96 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Emergency spare wheel	No
Repair kit	No

Bumper F, Scratch(es), Repair and paint (complete)





Bumper moulding F, Scratch(es), Smart repair



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Door trim RL, Scratch(es), Smart repair




Wing trim RL, Scratch(es), Smart repair



Bumper trim R, Scratch(es), Smart repair



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Replace and paint



Door trim RR, Scratch(es), Replace



Outside rear-view mirror housing R, Broken, Replace and paint



Wing trim FR, Scratch(es), Smart repair



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Outside rear-view mirror glass R, Broken, Replace



Kenteken	2DMV152
Merk Model	Peugeot 2008 GT 1.2 Puretech S&S 130pk/cv 5p EAT8
Brandstofsoort	Benzine
Datum deel1	4/28/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
10/17/25	12,936	klein materiaal	
10/17/25	12,936	luchtfilter interieur	Vervangen
10/17/25	12,936	oliezeef	Vervangen
10/17/25	12,936	onderhoud 2e jaar	Uitvoeren
10/17/25	12,936	remvloeistof	Vervangen
10/17/25	12,936	ruitwisserrubber vooraan	Vervangen
8/29/24	8,972	onderhoud 1e jaar	Uitvoeren