

» Overview

Order number: 1002396334
Order completed: 13.04.2026 12:19
Report number: 10408939
VIN: VSSZZZKJ1RR069441



Front Left 3/4



Rear Right 3/4



Mileage

» Vehicle Data

Vehicle category:	Passenger Car
Vehicle type:	Limousine
Make:	Seat
Model:	Arona
Manufacturers and type code:	7593 / ARI
Date of first registration:	18.01.2024
Mileage:	22,930 km
Proof of mileage:	ReadOff
Exterior colour:	"Urban" Silber
Roof colour:	"Urban" Silber
Propulsion:	Front
Fuel:	Petrol
Engine size (cc):	1,000 ccm
Performance:	81 kW (111 PS)
Length:	
Height:	
Width:	
Permitted total weight:	
Wheelbase:	
Number of powered axles:	2
Cylinders:	3
Euronorm:	Euro 6
Number of doors:	4
Number of seats:	5
Gearbox:	Automatic 7-speed
Upholstery type:	Lining fabrics
Interior colour:	Titanschwarz
Number of keys:	2

» Documents & Maintenance

Statutory inspection date:	
Registration certificate available:	Yes
Registration certificate received:	Yes
License plate:	None
Maintenance book:	Digital
Maintenance:	Not testable
Maintenance last date:	
Maintenance last mileage:	

"Standard Plus" version	Electronic differential lock XDS, dynamic traction support
2 reading lights in front	Electronic immobilizer
3-cylinder gasoline engine 1.0 l/81 kW TSI base engine: TJ4/TC5, "TSI", "eTSI"	Electronic stability control (ESC)
3-cylinder SI engine 1.0 l unit 05C.A	Emblems
3-point seat belt for center rear seat	Emission standard EU6 AP
3-point seat belts in front, with belt clamping device, without height adjustment	Equipment options subset for Germany
3-point seat belts, outer rear with ECE label	Extended and proactive pedestrian and cyclist protection
4 doors	Exterior mirror housings and various add-on parts in body color
6 speakers (passive)	Exterior mirrors, power-folding/adjustment, heated
7-speed automatic transmission "A7"	External, USB type C, only data socket(s)
Activated carbon canister (Evaporative Emission Control System (EVAP))	Forward collision warning incl. autonomous emergency braking, without adaptive cruise control
Airbag on driver and front passenger side, without knee airbag, with front passenger airbag deactivation	Fresh air intake system with combination filter
Alloy wheels 7J x 17	Front fog lamps
Alternator 140 A	Front head restraints
Antenna for AM/FM reception, "diversity"	Front stabilizer bar
Antifreeze up to -25 degree Celsius tolerance up to -30 degree C	Front-wheel drive
Axial and vertical adjustable steering column	Fuel system for fuel-injected SI engine (tropicalized)
Battery 320 A (49 Ah)	Gearshift knob/handle in leather
Breakaway interior rearview mirror, auto-dimming	Hand brake lever handle in leather
Breakdown kit	Hatchback
Carrier frequency 433.92 MHz-434.42 Mhz	Heat-reflecting windshield
Central locking w/ radio remote control, interior controls, without SAFELOCK	Heavy-duty rear axle (design 2)
Child seat anchors for child seat system ISOFIX	Hill start assist
Chrome package	Initial standard fuel filling
Climatronic with impact pressure control, CFC-free	In-plant control of self-collection
Control of series production	Installation differentiation for transmission DQ200 -- vehicle components --
Cruise control system and speed limiter	Instrument cluster, km/h speedometer
Data storage device for EU, integrated	Interior ambient lighting, type 1
Decorative inserts	Interior light in footwell in front and rear
Digital Cockpit	Lane keeping system
Digital radio reception	Leather-wrapped multi-function sports steering wheel with tiptronic
Disc brakes in front (Geomet D)	LED headlamps with lens
Disc brakes in rear (Geomet D)	LED license plate lighting
Door and side trim panel	LED rear combination lamp
Driver alert system	Left exterior mirror, convex
Driving on the right	Left-hand drive
Driving profile selection and conventional shock absorber	LongLife Service Regime
Dynamic headlight range control (self-adjusting while driving)	Luggage compartment cover, folding
ECO function	Luggage compartment trim (design 1)
	Manual height adjustment for front seats

Manual in German	Special price
Maps (Mapcare) Europe	Sports bumpers
Mirror Link plus Wireless "App" plus RSE (preparation)	Standard air cleaner
Mobile phone interface	Standard climatic zones
Multi-function display/trip computer active info display "Entry"	Standard dashboard
Nameplate set	Standard decorative trims
Navigation system	Standard design
Navigation system - High	Standard manufacturing sequence
No special edition	Standard paint coating
No special purpose vehicle, standard equipment	Standard pedal cluster
Non-smoker's package	Standard seats in front
Not hot country	Start-stop system with regenerative braking
Online service, with OCU, with head unit coding, without engine immobilizer interconnection	Sun visors with mirror, airbag label on front passenger sun visor
Operating permit, alteration	Suspension range 12 installation control only, no requirement forecast
Optional infotainment system (MIB3)	Three rear head restraints
Pan-European emergency call service	Tire pressure monitoring system
Part set without country-specific prescriptive standard	Tires 215/45 R17 91W xl
Power steering	Tires without specification of tire brand
Power windows with comfort operation and circuit breaker	Tool kit
Protective side molding	Top sports equipment
Rear exhaust tailpipe (standard)	Trims for alloy wheels
Rear floor panel module, type 1	Type approval country Germany
Rear fog lamp	Type sign and company logo
Rear overhang, short	Unsplit molded headliner
Rear shock absorption, sports version	Unsplit rear seat bench, split folding backrest
Rear window wiper and washer system with intermittent control	Variant
Reduced price package	Vehicle class differentiation -6F0-
Refrigerant R1234yf	Vehicles with special upgrade measures
Regional code " ECE " for radio	Vent
Right exterior mirror, convex	Visual and acoustic seat belt reminder, electric contact in front and rear
SEAT CONNECT gen3 - Media & Internet (online infotainment)	Voice control
SEAT CONNECT gen3 - Safety, service, remote access and online infotainment	Weight range 8 installation control only, no requirement forecast
SEAT Full LED	Wheel bolts with anti-theft protection (unlockable)
Seat trim covers in fabric	Wheelbase
Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature	Windshield wiper intermittent control with light/rain sensor
Service indicator 30 000 km or 2 years (variable)	With multifunction camera
Shock absorption in front	Without additional front underbody guard
Side airbag in front with curtain airbag	Without additional noise suppression measures for passenger compartment
Side and rear windows in heat-insulating glass	Without additional side body covers (stone guard)
Single-tone horn	Without additional tires
Special identification label for EC for M1 passenger vehicles	Without alternative drive system

Without applications

Without auxiliary heater/parking heater

Without backrest release for front seats

Without camera systems/accident sensors

Without CD changer/CD player

Without center armrest in front

Without customized installation

Without delivery equipment

Without drawers under front seats

Without dynamic road sign display

Without extended safety system

Without fire extinguisher

Without first aid kit and warning triangle

Without floor mats

Without headlamp washer system

Without heat accumulator/auxiliary heater

Without heated washer nozzles

Without lane change assist

Without light control

Without luggage nets/pockets on backrests

Without luggage/load compartment floor

Without lumbar support in seat backrests

Without mounting fixture in luggage compartment

Without park distance control

Without rear spoiler

Without roof insert (standard roof)

Without roof rails/roof load rack

Without seat heater

Without second battery

Without special body measures

Without special color trim

Without special specifications

Without surface protection, with additional transport protection measures

Without trailer hitch

Without UN-ECE cybersecurity & software update

Without washer fluid level indicator

» Tyres

MOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Falken	Front	Left	All season	Aluminium	215/45 R 17 91 W	4.0 mm
Falken	Front	Right	All season	Aluminium	215/45 R 17 91 W	4.0 mm
Falken	Rear	Left	All season	Aluminium	215/45 R 17 91 W	4.0 mm
Falken	Rear	Right	All season	Aluminium	215/45 R 17 91 W	5.0 mm

Permitted: Yes

Roadworthy: Yes

SPARE/EMERGENCY TYRE & ACCESSORIES

Repair kit present: Yes

Repair kit expiration date: 09.2027

Compressor present: Yes

No devaluation factors available

» Usage Damages

The vehicle shows signs of wear consistent with its age, mileage and purpose.

» Commercial devaluation

Known previous damages:	No
Previous damages detectable:	No
Repainting present:	No
Paint thickness measurement performed:	Yes - no abnormalities/deviations

PAINTHICKNESS MEASUREMENT RESULTS

The measured values were in the usual range.

At least 3 measurements were carried out per component.

» Notes On The Assessment

Details of the assignment and the scope of the assessment:

The order was placed to prepare a condition report on the described vehicle.

The vehicle condition assessment was carried out in accordance with the order on the basis of the standards for vehicle assessments specified by the client. The expert makes the findings in the individual case on the basis of his own expertise and at his own expert discretion.

Vehicle identification:

VSSZZZKJ1RR069441

VIN checked and matches documentation

Vehicle condition:

Cleaned

Inspection condition:

Sufficient

Lifting platform/lifting equipment used:

No

Testdrive carried out:

No

Engine test carried out:

Yes

» **Remarks**

This copy was generated electronically. It is valid without an original signature.

» Commercial Pictures



Front Left 3/4



Front Right 3/4



Rear Left 3/4



Rear Right 3/4



Mileage



Sill outer L



Sill outer R



Chassis nr




Wheel FL




Wheel FR



Wheel RL




Wheel RR



Central console



Engine compartment




Documents



Interior arrangement




Registration Certificate




History Maintenance



Interior - front



Interior - rear



Tirefit expiration date



GPS/Radio