



CITROËN BERLINGO: EQ-914-AP

Vinnumber:	VF77DBHW6HJ601379	Versionname:	CITROËN BERLINGO BlueHDi 75 BVM Club M VU [3P] bvm 5-75CH-5cv (fourgonnette-)
First Registrationdate:	24/08/2017	Fiscalpower:	
Expertise Mileage:	231891	Power Kw:	55
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 5 VIT	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	3		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	2	Tow bar	
Number keys remote	1	Radio	
Windows electric F		Sliding door right-side	
Type of climate control	Manual climate control	Seat cover lining	Lining Other

Tyres

	195/70/15/104 R			
Summer tyres:	Fr.L.	Other: 0%	Fr.R.	Other: 0%
	Re.L.	Other: 0%	Re.R.	Other: 0%
Tyre profile depth FL				8.6
Tyre profile depth FR				8.1
Tyre profile depth RL				8.9
Tyre profile depth RR				8.3
Tyre size FL				195/70 R 15 104 R
Tyre size FR				195/70 R 15 104 R
Tyre size RL				195/70 R 15 104 R
Tyre size RR				195/70 R 15 104 R
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				263
Tyre make FR				263
Tyre make RL				263
Tyre make RR				263

Assistance equipment

Spare wheel	Yes	Jack	Yes
Gear shift lever cover, Tear, Replace			



Steering wheel, Worn, Repair/replace (lump sum)



Floor mat F, Hole, Replace



Door seal FL, Tear, Replace



Inner door sill FL, Scratch(es), Paint



Wheel cover FR, Missing, Replace



Side wall RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bumper FR, Scratch(es), Repair and paint (complete)



Boot door lining L, Broken, Replace



Door hinge RL top, Missing, Replace



Boot door lining R, Broken, Replace



Historique Maintenance

Immatriculation: EQ-914-AP Date de 1ère immatriculation: 24/08/2017

Modèle: Citroen BERLINGO BlueHDi 75 BVM Club M VU [3P] bvm 5-75CH-5cv (fourgonnette-)

Date	Kilométrage	Fournisseur	Descriptif
06/02/2019	401.116	GARAGE DENIS DROUET	REPARATION DE ROUE
20/07/2022	157.801	GARAGE DENIS DROUET	DIAG
	0		TELECHARGEMENT CALCULATEUR
	0		DIVERS ECHAPPEMENT
30/06/2022	155.733	GARAGE DENIS DROUET	DIVERS ECHAPPEMENT
	0		DIVERS CLIM
	0		FILTRE A CARBURANT CTRL
	0		FILTRE CLIM RPLT
	0		REVISION
	0		BALAIS ESSUIE GLACE AV
	0		ANTIPOLLUTION
	0		ECLAIRAGE DE PLAQUE RPLT
	0		ADBLUE
	0		FAP RPLT
23/09/2021	130.262	GARAGE DENIS DROUET	REVISION ET CLIM ET AIR
27/07/2021	125.014	GARAGE DENIS DROUET	ECLAIRAGE DE PLAQUE RPLT
	0		LAMPE RPLT
	0		CONTROLE TECHNIQUE
26/02/2021	110.820	GARAGE DENIS DROUET	DISQUES PLAQUETTES AV RPLT
07/12/2020	103.160	GARAGE DENIS DROUET	SONDE LAMBDA RPLT
26/11/2020	102.214	GARAGE DENIS DROUET	REVISION ET CLIM ET AIR ET CARBURANT
	0		LAMPE CODE AVD RPLT
	0		LAMPE CODE AVD RPLT
	0		BALAIS ESSUIE GLACE AV
	0		PLAQUETTES AR RPLT
	0		ADBLUE
	0		DIVERS ECHAPPEMENT
26/02/2020	75.718	GARAGE DENIS DROUET	LAMPE CODE AVD RPLT
	0		ADBLUE
	0		ECLAIRAGE DE PLAQUE RPLT
	0		REVISION ET CLIM
03/10/2019	59.528	GARAGE DENIS DROUET	PLAQUETTES AV RPLT

Historique Maintenance

Immatriculation: **EQ-914-AP**

Date de 1ère immatriculation: **24/08/2017**

Modèle: **Citroen BERLINGO BlueHDi 75 BVM Club M VU [3P] bvm 5-75CH-5cv (fourgonnette-)**

Date	Kilométrage	Fournisseur	Descriptif
	0		LAMPE RPLT
01/07/2019	50.211	GARAGE DENIS DROUET	REVISION ET CLIM ET AIR ET CARBURANT
	0		LIQUIDE DE FREIN
05/02/2019	38.477	GARAGE DENIS DROUET	LAMPE CODE AVD RPLT
17/07/2018	24.540	GARAGE DENIS DROUET	ADBLUE
	0		REVISION ET CLIM