MACADAM











BMW 1 Reeks (UKL): 2DHE338

Vinnumber:	**WBA7K110207L86082**	Versionname:	**116i (F40) 1.5i 109pk/cv 5p**
First Registrationdate:	**20/03/2023**	Fiscalpower:	
Expertise Mileage:	**121766**	Power Kw:	**80**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**01/11/2027**		
Maintenance	**19000.0**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**205/55/16/91 V**			
	Fr.L.	**Vredestein: 7 mm**	Fr.R.	**Vredestein: 7 mm**
	Re.L.	**Fulda: 7 mm**	Re.R.	**Fulda: 7 mm**

Tyre profile depth FL	**7.0**
Tyre profile depth FR	**7.0**
Tyre profile depth RL	**7.0**
Tyre profile depth RR	**7.0**
Tyre size FL	**205/55 R 16 91 V**
Tyre size FR	**205/55 R 16 91 V**
Tyre size RL	**205/55 R 16 94 V**
Tyre size RR	**205/55 R 16 94 V**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**2480**
Tyre make FR	**2480**
Tyre make RL	**2484**
Tyre make RR	**2484**

Assistance equipment

Seat cover FL, Worn, Acceptable







Windscreen, Stone chip(s), Replace







Alloy rim RR, Scratch(es), Repair and paint (complete)





Outside rear-view mirror base R, Scratch(es), Acceptable




Alloy rim FR, Scratch(es), Repair and paint (complete)





Bodywork, Paint measurement, Acceptable



Bodywork, Not original part, Remove lettering






Onderhoudshistorie van: WBA7K110207L86082

ALPHABET

Kenteken	2DHE338
Merk Model	BMW 116i (F40) 1.5i 109pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	3/20/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
11/4/25	109,324	batterij	Vervangen
11/4/25	109,324	BMW/MINI service standaard omvang	Uitvoeren
11/4/25	109,324	BMW/MINI voertuigcontrole	Uitvoeren
11/4/25	109,324	klein materiaal	
11/4/25	109,324	koelwatervloeistof	Bijvullen/-laden
11/4/25	109,324	remblokken achter	Vervangen
11/4/25	109,324	remblokken vooraan	Vervangen
11/4/25	109,324	remvloeistof	Vervangen
11/4/25	109,324	ruitenwisservloeistof	Bijvullen/-laden
11/4/25	109,324	service microfilter	Uitvoeren
11/4/25	109,324	service motorolie	Uitvoeren
6/17/25	96,506	controle niveaus	Uitvoeren
11/13/24	74,722	BMW/MINI service standaard omvang	Uitvoeren
11/13/24	74,722	BMW/MINI voertuigcontrole	Uitvoeren
11/13/24	74,722	bougie	Vervangen
11/13/24	74,722	klein materiaal	
11/13/24	74,722	service luchtfilter	Uitvoeren
11/13/24	74,722	service microfilter	Uitvoeren
11/13/24	74,722	service motorolie	Uitvoeren
9/3/24	63,444	BMW/MINI service standaard omvang	Uitvoeren
9/3/24	63,444	controle niveaus	Uitvoeren
9/3/24	63,444	klein materiaal	
9/3/24	63,444	remblokken achter	Vervangen
2/1/24	39,796	service microfilter	Uitvoeren
2/1/24	39,796	service motorolie	Uitvoeren