



RENAULT Clio: 2657-MFJ

Vinnumber:	VF1RJA00570410196	Versionname:	Business Blue dCi 74kW (100CV) berlina con portón
First Registrationdate:	7/03/2023	Fiscalpower:	74kW 5P manual
Expertise Mileage:	214087	Power Kw:	
Bodytype:	Berline	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning:	No		
Battery functioning:	No		
Vehicle running:	No		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	No		

Options

Number of keys total:	1	Luggage cover:	
Number keys remote:	1		
Windows electric F:			
Cruise Control:			
Steering wheel multifunctional:			
Steering wheel leather:			
Radio multimedia:			
Type of climate control:	Manual climate control		

Tyres

185/65/15/88 H				
Summer tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm
Tyre profile depth FL:				3.0
Tyre profile depth FR:				3.0
Tyre profile depth RL:				3.0
Tyre profile depth RR:				3.0
Tyre size FL:				185/65 R 15 88 H
Tyre size FR:				185/65 R 15 88 H
Tyre size RL:				185/65 R 15 88 H
Tyre size RR:				185/65 R 15 88 H
Tyre type FL:				Summer
Tyre type FR:				Summer
Tyre type RL:				Summer
Tyre type RR:				Summer
Tyre make FL:				259
Tyre make FR:				259
Tyre make RL:				259
Tyre make RR:				259

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
Registration document, Missing, Repair/replace (lump sum)			



Ignition key, Missing, Repair/replace (lump sum)



Interior, Dirty, Cleaning




Backrest cover FL, Hole, Replace



Interior covering A pillar L, Burned, Replace



Roof liner, Burned, Replace



Wheel cover FL, Broken, Replace



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Door RR, Dent(s), Repair and paint (complete)



Outer door handle FR, Scratch(es), Paint



Wheel cover FR, Scratch(es), Replace



Wing FR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Boot carpet, Tear, Replace



Tyres, No damage, Check



Bodywork, Glue residues, Remove lettering



