


2-EDF-564

2-EDF-564 · 530e Touring Business Pakket · 30 March 2026 · Zaventem (BE)

Specifications

License Plate Number	2-EDF-564	Fuel Type	Hybrid Gasoline
Manufacturer	BMW	VIN	WBA11CG070CP13255
Model	5-SERIE	Cylinder Capacity	1.998 ^{cm³}
Model Versions	530e Touring Business Pakket	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	04-09-2023
Color	Blue	Odometer	85.189 ^{km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2023	Interior	Black
KW	135	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Charging cable - 230v

Charging cable - 380v

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Electrically adjustable front seats

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Steeringwheel - Heated

Condition

Condition exterior	Adequate	Maintenance Remarks	Olie verversen over 17000 km
Condition interior	Adequate	Previous Repairs	Unknown
Last Maintenance	Unknown		

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	7 ^{mm}	Tigar	245 ^{mm}	45 ^{mm}	18 ^{inch}	Summer
Rear Left	8 ^{mm}	Tigar	245 ^{mm}	45 ^{mm}	18 ^{inch}	Summer
Front Right	7 ^{mm}	Tigar	245 ^{mm}	45 ^{mm}	18 ^{inch}	Summer
Rear Right	8 ^{mm}	Tigar	245 ^{mm}	45 ^{mm}	18 ^{inch}	Summer
Spare Tire Type		None				

Damages



Damage Part
Frontdoor - Left

Damage Type
Door-edge chipped

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Windscreen - Front

Damage Type
Chipped

Repair Type
Window Repair

Acceptable
No



Damage Part
Hood

Damage Type
Stonechipping

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Bumper - Front

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Mirror - Rightside

Damage Type
Scratch(es)

Notes
Richtingaanwijzer

Repair Type
Replace

Acceptable
No



Damage Part
Mirror - Rightside

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Right	Small scratch(es)	Touch-up / Polish	No



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor - Left	Door-edge chipped	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Rear Left	Small dent(s)	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Scratch(es)	Spray	No



Damage Part
Fender - Rear Left

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Tailgate

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Windscreen - Rear

Damage Type
Small scratch(es)

Repair Type
Repair

Acceptable
No



Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No