

INSPECTION REPORT

End of contract

GENERAL INFO

File	316319
License plate	2CEL153
Vehicle identification number	WBA6N91080FN12257
Dossier	2022171124
Make	BMW 320e Touring
Mileage	164573
First registration	23/06/2022
client availability date	25/06/2026
inspectionDate	08/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
32	Front Bonnet // Painting	Y
40	Windshield // Repair	Y
63	Wing Front Left // Painting	N
83	Door Front Left // Painting	Y
92	Rocker Panel Left // Painting	Y
103	Door Rear Left // Painting	Y
136	Bumper Rear // Polish	Y
153	Rear Bonnet // Painting	Y
161	Roof // Smart Repair Medium	Y
174	Light / Rear Right / Replace	Y
180	Wing Rear Right // Smart Repair Small	Y
194	Door Rear Right // Repair & Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
210	Door Front Right // Smart Repair Small	Y
236	Wing Front right // Polish	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
568	Dashboard / Ventilation Outlet / Replace	N
641	Rear Right Door Interior Coating // Repair	N
860	Interior Cleaning // Small	N


Damage Pictures



Bumper Rear // Polish-scratch



Rear Bonnet // Painting-scratch



Light / Rear Right / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Wing Front right // Polish-scratch




Front Bonnet // Painting-scratch



Door Front Left // Painting-scratch



Door Rear Left // Painting-scratch



Rocker Panel Left // Painting-scratch



Door Front Right // Smart Repair Small-scratch




Rear Right Door Interior Coating // Repair-scratch



Roof // Smart Repair Medium-dent



Wing Rear Right // Smart Repair Small-dent



Door Rear Right // Repair & Painting-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Dashboard / Ventilation Outlet / Replace-cracked



Windshield // Repair-glass damage



Interior Cleaning // Small-stain



Wing Front Left // Painting-stone chipping