MACADAM







BMW 520d xDrive Touring: 1YBQ044

Vinnumber:	**WBA51BN060CG82369**	Versionname:	
First Registrationdate:	**8/03/2021**	Fiscalpower:	
Expertise Mileage:	**155904**	Power Kw:	
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Diesel**		
Maintenance	**NOT OK**		
Maintenance	**uitvoeren**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		
Registration Certificate Home (BE)	**Yes**		

Options

Number of keys total	**1**	Type of Tow bar	**No Tow bar**
GPS			
Type of headlighting	**Headlighting LED**		
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**245/35/20/95 Y**			
	Fr.L.	**Goodyear: 3 mm**	Fr.R.	**Goodyear: 4 mm**
	Re.L.	**Michelin: 5 mm**	Re.R.	**Michelin: 5 mm**

Tyre profile depth FL	**3.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**245/35 R 20 95 Y**
Tyre size FR	**245/35 R 20 95 Y**
Tyre size RL	**275/30 R 20 97 Y**
Tyre size RR	**275/30 R 20 97 Y**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Number of charging cables (normal)	**0**	Runflat	**Yes**
Number of charging cables (rapid charge)	**0**		

Service, Maintenance, Execute



MOT certificate, Extra mileage, Check




Instrument panel, complete, Not functioning (well), Check



Steering wheel, Scratch(es), Acceptable




Door panel RR, Scratch(es), Acceptable




Ignition key, Missing, Replace



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)










Bonnet, Scratch(es), Polish




Tyre FL, Tear, Replace




Alloy rim FL polished, Scratch(es), Repair and paint (complete)




Wing FL, Scratch(es), Acceptable




Mirror side repeater L, Broken, Replace




Door FL, Scratch(es), Acceptable




Step L, Scratch(es), Acceptable




Wing RL, Scratch(es), Acceptable




Luggage compartment cover, Missing, Replace



Boot lid covering R, Scratch(es), Acceptable




Bumper R, Scratch(es), Repair and paint (complete)










Wing RR, Dent(s) and scratch(es), Repair and paint (complete)








Door RR, Scratch(es), Repair and paint (complete)






Door FR, Scratch(es), Acceptable




Mirror side repeater R, Crack, Replace




Outside rear-view mirror base R, Scratch(es), Acceptable




Tyre FR, Tear, Replace




Alloy rim FR polished, Scratch(es), Repair and paint (complete)




Bodywork, Paint measurement, Acceptable


148