# VEHICLE REPORT

IT · 02/11/2026
2026-11-02 13:14

VIN: Targa: Merchant:

## VEHICLE DETAILS

| | | | |
|---|---|---|---|
| Targa | | First Registration | **2019-05-28** |
| Marca | N/A | Mileage | N/A |
| Modello e Allestimento | | Keys | N/A |
| VIN | | Owners | **7** |
| Merchant | | Seats | **5** |
| Branch | | Previous Use | **AUTOVEICOLO PROPRIO AUTOVETTURA PER TRASPORTO DI PERSONE** |
| KW | **88** | VAT | N/A |
| CC | **0** | Country | **IT** |
| Fuel | **BENZ** | Euro | **EURO6** |
| GPL | **31/08/2022** | Cambio | **Non presente** |
| Gancio | N/A | | |

## CAR PHOTOS (58)


*Front*


*Roof*


*Engine compartment*


*Engine compartment*


*Hood*


*Engine compartment*


*Center console and dashboard*


*Center console and dashboard*


*Center console and dashboard*


*Navigation on.*


*Interior front*


*Interior front*


*Speedometer with started engine*


*Interior front*


*Interior front*


*Interior rear*


*Interior rear*


*Interior front*


*Interior front*


*Interior front*


*Front door left*


*Roof*


*Rear fender left*


*Left side rear*


*Front door left*


*Left side front*


*Front left*


*Front left*


*Roof.*


*Additional photos (optional)*


*Additional photos (optional)*


*Rear fender left*


*Left side front*


*Front door left*


*Front door left*


*Front door left*



Additional photos (optional)



Additional photos (optional)



Additional photos (optional)



Rear fender left



Rear fender right



Additional photos (optional)



Additional photos (optional)



Additional photos (optional)



Additional photos (optional)



Additional photos (optional)



Additional photos (optional)



Front left



Left side front



Left side front



Right side rear



Trunk



Rear



Right side rear



Left side front



Left side front



Front left



Front