



Seat Arana (UKL): 2CCT096

Vinnnumber:	VSSZZZKJZNR086316	Versionname:	Arana Move! 1.0TSi 95pk/cv 5p
First Registrationdate:	7/06/2022	Fiscalpower:	
Expertise Mileage:	58559	Power Kw:	70
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 5 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	over 22000 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/60/16/96 H			
Summer tyres:	Fr.L.	Hankook: 4 mm	Fr.R.	Hankook: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/60 R 16 96 H
Tyre size FR				205/60 R 16 96 H
Tyre size RL				205/60 R 16 96 V
Tyre size RR				205/60 R 16 96 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				260
Tyre make FR				260
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Spare wheel	Yes	Jack	Yes
Windscreen, Stone chip(s), Acceptable			





Bonnet, Scratch(es), Acceptable



Step L, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Wing RL, Dent(s), Paintless dent repair



Wing RL, Scratch(es), Acceptable



Wing trim RL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Rear window, Scratch(es), Replace



Bumper trim R, Scratch(es), Replace



Bumper moulding R, Scratch(es), Acceptable



Bumper moulding R, Scratch(es), Replace



Wing trim RR, Scratch(es), Replace



Door RR, Scratch(es), Acceptable



Bodywork, Not original part, Remove lettering



Kenteken	2CCT096
Merk Model	Seat Arona Move 1.0TSi 95pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	6/7/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
5/8/26	51,446	bougie	Vervangen
5/8/26	51,446	klein materiaal	
5/8/26	51,446	koelwatervloeistof	Bijvullen/-laden
5/8/26	51,446	remvloeistof	Bijvullen/-laden
5/8/26	51,446	ruitenwisserrubber achter	Vervangen
5/8/26	51,446	ruitenwisserrubber vooraan	Vervangen
5/8/26	51,446	ruitenwisservloeistof	Bijvullen/-laden
5/8/26	51,446	Tussentijdse onderhoudsbeurt (variabel	Uitvoeren
1/30/25	27,959	klein materiaal	
1/30/25	27,959	koelwatervloeistof	Bijvullen/-laden
1/30/25	27,959	luchtfILTER interieur	Vervangen
1/30/25	27,959	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
1/30/25	27,959	remblokken vooraan	Vervangen
1/30/25	27,959	ruitenwisserrubber achter	Vervangen
1/30/25	27,959	ruitenwisserrubber vooraan	Vervangen
1/30/25	27,959	ruitenwisservloeistof	Bijvullen/-laden
9/28/23	12,354	klein materiaal	Uitvoeren
9/28/23	12,354	koelwatervloeistof	Uitvoeren
9/28/23	12,354	ruitenwisservloeistof	Bijvullen/-laden
9/28/23	12,354	Tussentijdse onderhoudsbeurt (variabel	Uitvoeren