MACADAM









CITROÃ‹N C3 AIRCROSS: GE-434-RQ

Vinnumber:	**VF72CYHSMN4147310**	Versionname:	**CITROÃ‹N C3 AIRCROSS BlueHDi 110 S&S BVM6 Shine Pack VP [5P] bvm 6-110CH-6cv (SUV)**
First Registrationdate:	**15/02/2022**	Fiscalpower:	
Expertise Mileage:	**98286**	Power Kw:	**81**
Bodytype:	**SUV**	Body colour	**Grey**
Gearbox:	**MAN 6 VIT**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**1**	Radio	
Number keys remote	**1**	Luggage cover	
GPS big screen color		Headlights Xenon/LED/Laser	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Roof bar black	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	**Lining Other** **Lining Leather**
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**215/50/17/95 W**			
	Fr.L.	**Kleber: 65%**	Fr.R.	**Kleber: 70%**
	Re.L.	**Kleber: 55%**	Re.R.	**Kleber: 50%**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**3.8**
Tyre profile depth RL	**4.7**
Tyre profile depth RR	**4.8**
Tyre size FL	**215/50 R 17 95 W**
Tyre size FR	**215/50 R 17 95 W**
Tyre size RL	**215/50 R 17 95 W**
Tyre size RR	**215/50 R 17 95 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**2479**
Tyre make FR	**2479**
Tyre make RL	**2479**
Tyre make RR	**2479**

Assistance equipment

Interior, Stain, Cleaning









Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Tyre FL, Out of tolerance, Replace





Tyre FR, Out of tolerance, Replace





Door FL, Dent(s) and scratch(es), Repair and paint (complete)







Door RL, Dent(s) and scratch(es), Repair and paint (complete)







Wing RL, Dent(s), Acceptable




Windscreen, Stone chip(s), Replace




Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Bumper moulding F, Scratch(es), Replace




Bumper spoiler F, Scratch(es), Acceptable






Door FR, Dent(s) and scratch(es), Repair and paint (complete)





Wing RR, Dent(s), Acceptable




Internal boot lining L, Scratch(es), Repair/replace (lump sum)




Internal boot lining R, Scratch(es), Replace





Luggage cover stopper, Missing, Replace




Bumper moulding R, Scratch(es), Acceptable





Bumper R, Scratch(es), Repair and paint (complete)




ALPHABET

Historique Maintenance

Immatriculation: **GE-434-RQ** Date de 1ère immatriculation: **15/02/2022**

Modèle: **Citroen C3 AIRCROSS BlueHDi 110 S&S BVM6 Shine Pack VP [5P] bvm 6-110CH-6cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
09/02/2026	85.966	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
08/06/2026	85.262	PARASCANDOLA-CTO	REVISION ET CLIM ET AIR ET CARBURANT
			REVISION ET CLIM ET AIR ET CARBURANT
			LIQUIDE DE FREIN
			REVISION ET CLIM ET AIR ET CARBURANT
			REVISION ET CLIM ET AIR ET CARBURANT
			LIQUIDE DE REFROIDISSEMENT RPLT
19/12/2025	81.863	PARASCANDOLA-CTO	SOUFFLET DE CARDAN RPLT
05/06/2025	68.286	PARASCANDOLA-CTO	BALAI ESSUIE GLACE AR
			FILTRE A AIR RPLT
			REVISION
			FILTRE CLIM RPLT
			REVISION
			BALAIS ESSUIE GLACE AV
			DISQUES PLAQUETTES AV RPLT
06/09/2024	53.140	CHOPARD CANNES MOUGINS	FILTRE CLIM RPLT
			REVISION
			PILE DE CLE RPLT
			LIQUIDE DE FREIN
			RECYCLAGE
22/08/2023	27.582	CHOPARD CANNES MOUGINS	BALAIS ESSUIE GLACE AV
			FILTRE CLIM RPLT
			REVISION
			RECYCLAGE
			BALAI ESSUIE GLACE AR