BMW 3 SERIES TOURING

Vehicle information

Make:	**BMW**	License:	**2CGD875**
Gearbox:		Body color:	
Model:	**3 SERIES TOURING**	VIN:	**WBA6N71020FN23629**
Fuel type:		Power:	**135 kW**
Version:	**2.0 330E (215KW) XDRIVE TOURING**	First registration	**12/07/2022**
Mileage:	**104274 km**	N° of doors:	

Damage summary

Front	1
Interior	6
Rear	1
Roof & others	1

Commercial pictures
































Options according to the inspector

GPS	**Yes**

Tyres

Front Left
Summer
Aluminium
225/50/17/98/W
Hankook
6.0 mm
Front Right
Summer
Aluminium
225/50/17/98/W
Hankook
6.0 mm
Rear Left
Summer
Aluminium
225/50/17/98/W
Hankook
6.0 mm
Rear Right
Summer
Aluminium
225/50/17/98/W
Hankook
6.0 mm

Checks

Battery level	**100**	Category	**Passenger Car**
Certificate of Conformity	**Yes**	Compressor	**N/A**
Maintenance	**OK**	Maintenance	**6000 km - 01/2028**
Number of charging cables (normal)	**0**	Number of charging cables (rapid charge)	**0**
Number of keys total	**2**	Registration Certificate Car (BE)	**Yes**
Registration Certificate Home (BE)	**No**	Repair kit	**N/A**
Reset to factory settings	**Yes, vehicle is reset to factory settings**	Statutory inspection	**OK**
Statutory inspection	**12/07/2028**	Type of Maintenance book	**Digital maintenance**

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.