



Opel Mokka: N411XH

Vinnumber:	VXKUKZKXZMW089056	Versionname:	Mokka 100kW/50kWh (11kW) Business Elegance automaat
First Registrationdate:	4/02/2022	Fiscalpower:	
Expertise Mileage:	58168	Power Kw:	100
Bodytype:		Body colour	White
Gearbox:	Automatic	Paint type	Opaque
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	731
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Lining semi-leather
GPS		Rear parking sensors
Autom climate control		Rear view camera
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 60 / 17 / 100 / H / Aluminium	8,2 mm	Bridgestone	Summer
	Right	215 / 60 / 17 / 100 / H / Aluminium	7,9 mm	Bridgestone	Summer
Rear	Left	215 / 60 / 17 / 100 / H / Aluminium	8,2 mm	Bridgestone	Summer
	Right	215 / 60 / 17 / 100 / H / Aluminium	8,0 mm	Bridgestone	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Interior, Dirty, Cleaning



Door RL, Bad repair, Repair and paint (complete)



Door FL, Bad repair, Repair and paint (complete)



Wing FL, Bad repair, Repair and paint (complete)



Bonnet, Scratch(es), Repair and paint (complete)



Door RR, Dent(s), Repair and paint (complete)



Bumper moulding R, Scratch(es), Replace and paint



Boot cover, Missing, Replace



Bumper R, Scratch(es), Repair and paint (complete)



Kenteken	N411XH
Merk Model	Opel Mokka 100kW/50kWh (11kW) Business Elegance automaat
Brandstofsoort	Elektrisch
Datum deel1	04-02-22

Datum reparatie	Kilometerstand	Reparatie omschrijving
09-01-26	54.270	APK
09-01-26	54.270	Onderhoudsbeurt
09-01-26	54.270	Sleutelbatterij
11-01-24	30.710	Onderhoudsbeurt
24-05-23	13.350	Onderhoudsbeurt