MACADAM










PEUGEOT PARTNER: FN-842-WJ

Vinnumber:	**VR3EFYHYCKJ840711**	Versionname:	**PEUGEOT PARTNER BLUEHDI 100 S&S 650KG STAND ASPHALT VU [4P] bvm 5-102CH-5cv (fourgonnettesimple cabine)**
First Registrationdate:	**19/02/2020**	Fiscalpower:	
Expertise Mileage:	**121135**	Power Kw:	**75**
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 5 VIT**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**2**		
Number head rests	**2**		
Type of rims (mounted)	**Steel**		
Category	**Light Commercial Vehicle**		

Options

Number of keys total	**2**	Tow bar	
Number keys remote	**1**	Radio	
GPS big screen color		Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control		Sliding door right-side	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	**Lining Other**
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**195/65/15/91 H**			
	Fr.L.	**Goodyear: 45%**	Fr.R.	**Goodyear: 45%**
	Re.L.	**Goodyear: 35%**	Re.R.	**Goodyear: 50%**

Tyre profile depth FL	**5.4**
Tyre profile depth FR	**5.1**
Tyre profile depth RL	**5.8**
Tyre profile depth RR	**4.9**
Tyre size FL	**195/65 R 15 91 H**
Tyre size FR	**195/65 R 15 91 H**
Tyre size RL	**195/65 R 15 91 H**
Tyre size RR	**195/65 R 15 91 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Inner door sill FL, Scratch(es), Paint






Interior, Dirty, Cleaning






Air vent, mid-dashboard, Damaged, Replace







Bumper F, Deformed / Strained, Repair and paint (complete)








Boot door panel RL, Scratch(es), Polish






Bumper R, Deformed / Strained, Repair and paint (complete)






Bodywork, Not original part, Sticker removal small







ALPHABET

Historique Maintenance

Immatriculation: **FN-842-WJ** Date de 1ère immatriculation: **19/02/2020**

Modèle: **Peugeot PARTNER BLUEHDI 100 S&S 650KG STAND ASPHALT VU [4P] bvm 5-102CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
02/07/2026	121.048	SARL LES DUNES	ARBRE A CAMES RPLT
04/03/2026	113.091	SARL LES DUNES	REVISION
			FILTRE CLIM RPLT
			FILTRE A AIR RPLT
			REVISION
			DIVERS CLIM
			ADBLUE
			LAMPE RPLT
			BALAIS ESSUIE GLACE AV
			RECYCLAGE
04/03/2026	110.673	SARL LES DUNES	DIVERS CARROSSERIE
18/06/2025	98.213	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS ETE
16/10/2024	81.002	FLEET SOLUTIONS FRANCE	REPARATION DE ROUE
14/05/2024	69.615	SARL DEHEEGHER	INJECTEUR ADBLUE RPLT
			DIVERS
19/04/2024	67.127	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS ETE
21/03/2024	66.181	SARL DEHEEGHER	PLAQUETTES AV RPLT
			BALAIS ESSUIE GLACE AV
31/10/2023	56.614	SOFIDAP	ADBLUE
31/10/2023	56.614	SOFIDAP	CHAINES NEIGE RPLT
31/10/2023	55.916	SOFIDAP	FILTRE A AIR RPLT
			BRAS ESSUIE GLACE RPLT
			REVISION
			FILTRE CLIM RPLT
			LIQUIDE DE FREIN
			REVISION
26/01/2023	40.201	NORAUTO SAS (PRODUIT SPE)	REMPLACEMENT PNEUS ETE
17/02/2022	17.226	SARL DEHEEGHER	FILTRE CLIM RPLT
			REVISION
			BALAIS ESSUIE GLACE AV
			LIQUIDE DE FREIN
30/03/2021	9.160	NORAUTO SAS (PRODUIT SPE)	REPARATION DE ROUE

Historique Maintenance

Immatriculation: **FN-842-WJ** Date de 1ère immatriculation: **19/02/2020**

Modèle: **Peugeot PARTNER BLUEHDI 100 S&S 650KG STAND ASPHALT VU [4P] bvm 5-102CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
10/09/2020	4.744	NORAUTO SAS (PRODUIT SPE)	REPARATION DE ROUE