



Mercedes Vito

Vinnumber:	W1VVLGEZ9P4246957	Versionname:	
First Registrationdate:	13/04/2023	Fiscalpower:	
Expertise Mileage:	196616	Power Kw:	120
Bodytype:		Body colour:	White
Gearbox:	Automatic	Type of rims (mounted):	Steel
Transmission:		Parking lot:	3716
Fueltype:	Diesel		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Rear parking sensors:	
Cruise Control:		Type of Tow bar:	Tow bar fixed
Steering wheel multifunctional:			
Radio multimedia:			
Type of headlighting:	Headlighting Halogen		
Type of GPS:	No GPS		
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		

Limited Technical Inspection

Tyres

	225/55/17/92 H			
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/55 R 17 92 H
Tyre size FR				225/55 R 17 92 H
Tyre size RL				225/55 R 17 92 H
Tyre size RR				225/55 R 17 92 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	1790,14
Floor covering FL, Damaged, Smart repair:	116,69



Seat cover FL, Stain, Cleaning 29,16



Interior, Damaged, Acceptable 0,00



Seat cover FR, Stain, Cleaning 29,16



Dashboard, Glue residues, Cleaning 29,16



Dashboard, Hole, Smart repair 116,69



Bumper F, Scratch(es), Acceptable 0,00



Wing RL, Dent(s), Acceptable 0,00



Door FL, Dent(s), Acceptable 0,00



Step L, Scratch(es), Acceptable 0,00



Outer sill L, Bad repair, Check 0,00



Bumper R, Dent(s), Replace 187,63



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete) 506,94



Door RR, Dent(s) and scratch(es), Repair and paint (complete) 334,34



Wing RR, Dent(s), Repair and paint (complete) 323,68



Outside rear-view mirror cover R (upper), Scratch(es), Smart repair 116,69

