



IDENTIFICATION VEHICLE

Driver name:
Make: FORD
Model / version: TRANSIT 2T 350M FOU MWB HR
 DSL
Vin: WF0XXXTTGXKE41004
Plate: 1XFH885
Mileage: 91475
First registration: 13/12/2019
Color: Frozen white


ADDITIONAL INFORMATION





Category:
Transmission:
Interior color:
Metallic paint: ?
Type of lining:
Board computer reset: ?

DOCUMENTS

Certificate of conformity: ✓
Registration certificate: ✓
Registration certificate 2: ✓
Insurance certificate: ?
Maintenance book:
Number of keys: 2
Original key: ✓

PICTURES





VIN INFORMATION

Radio
Prise USB
Traction avant
Fourgon tôle
Pavillon normal
Usine de fabrication Turquie
Bavettes arrière
Diamètre avant 16
Largeur arrière 6,5
Hauteur avant 65
Indice de vitesse arrière R
Diamètre 16
Diesel
96 kw
TDCi

4 haut-parleurs
Boîte manuelle
Porte latérale droite coulissante
3 300 mm
2019
Projecteurs antibrouillard
Matière : tôle
Diamètre arrière 16
Diamètre avant 16
Hauteur arrière 65
Largeur avant 215
Climatisation
1996 cm3
130 ch
Unie vernissée

Bluetooth
6 rapports
Porte latérale droite tôle
3 500 kg
Février
Bavettes avant
Lettre repère (J)
Largeur avant 6,5
Diamètre arrière 16
Indice de vitesse avant R
Largeur arrière 215
Ordinateur de bord
2.00 litres
Euro 6
Rétroviseur gauche à réglage électrique

Rétroviseur droit à réglage électrique	Rétroviseur gauche chauffant	Rétroviseur droit chauffant
Siège avant gauche chauffant	Sièges avant chauffants	Siège avant gauche à réglage lombaire
Sièges avant à réglage lombaire	Aide au stationnement avant	Aide au stationnement arrière
Régulateur et limiteur de vitesse	Airbag conducteur	Airbag passager
boîte à gants verrouillable	haut-parleurs ar	éclairage adaptatif
éclairage habitacle avec LED	"Ford Easy Fuel"	grille de calandre grise

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	×	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	×
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			All-seasons		?
Front right	5 mm			All-seasons		?
Rear left	5 mm			All-seasons		?
Rear right	5 mm			All-seasons		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
2	Bodywork - Stickers	Not original part
3	Indicator FL	Broken
4	Bumper corner RR	Deformed / Strained

Total: 3

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
1	Bodywork	Not original part	✓	×	×

Total: 1

DAMAGES DETAILS

2 - Bodywork - Stickers - Not original part




3 - Indicator FL - Broken



4 - Bumper corner RR - Deformed / Strained



1 - Bodywork - Not original part - Renta®



SIGNATURE