



Volkswagen Caddy: VGP46S

Vinnumber:	WV1ZZZ2KZLX117929	Versionname:	Caddy Maxi 1.4 TGI 81kW Ecofuel
First Registrationdate:	30/10/2020	Fiscalpower:	
Expertise Mileage:	100543	Power Kw:	81
Bodytype:		Body colour	Candywit
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:		Type of rims (mounted)	Steel
Fueltype:	Gas	Parking lot	937
Number of seats	2		
Type of rims (mounted)	Steel		
Maintenance needed	No		

Options

Number of keys total	1	Rear parking sensors
Manual climate control		Sliding door right-side
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 65 / 15 / 95 / H / Steel	4,7 mm	Continental	All season
	Right	195 / 65 / 15 / 95 / H / Steel	4,7 mm	Continental	All season
Rear	Left	195 / 65 / 15 / 95 / H / Steel	7,5 mm	Continental	All season
	Right	195 / 65 / 15 / 95 / H / Steel	7,0 mm	Continental	All season

Assistance equipment

Ignition key, Missing, Replace

No pictures to display

Interior, Dirty, Cleaning



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Door trim FL, Dent(s) and scratch(es), Replace



Wing RL, Dent(s), Paintless dent repair



Bumper F, Scratch(es), Smart repair



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Door trim FR, Broken, Replace



Side wall panel RR, Scratch(es), Replace



Tailgate / Boot, Dent(s), Repair and paint (complete)



Bumper R, Scratch(es), Smart repair



Bodywork, Chemical polution, Polish



Kenteken	VGP46S
Merk Model	Volkswagen Caddy Maxi 1.4 TGI 81kW Ecofuel
Brandstofsoort	CNG
Datum deel1	30-10-20

Datum reparatie	Kilometerstand	Reparatie omschrijving
13-01-26	91.450	APK
13-01-26	91.450	Luchtfilter
13-01-26	91.450	Onderhoudsbeurt
13-01-26	91.450	Remklauw(en) voorzijde
13-01-26	91.450	Remschijf + blokken voor
13-01-26	91.450	Remvloeistof
13-01-26	91.450	Ruitenwisserblad(en) voorzijde
20-02-25	79.239	Accu
20-02-25	79.239	Boordcomputer
20-02-25	79.239	Vervanging band
27-11-24	75.634	Accu
27-11-24	75.634	APK
27-11-24	75.634	Remblokken achterzijde
27-11-24	75.634	Remblokken voorzijde
27-11-24	75.634	Vervanging band
27-11-24	75.634	Viergas meting
20-11-24	0	Accu
12-07-24	0	Accu
06-05-24	66.146	Onderhoudsbeurt
19-10-23	56.572	APK
19-10-23	56.572	Remblokken achterzijde
19-10-23	56.572	Remblokken voorzijde
19-10-23	56.572	Uitlijnen voor en achterwielen
21-07-23	52.082	Bougie
21-07-23	52.082	CNG-tank keuring
21-07-23	52.082	Onderhoudsbeurt
21-07-23	52.082	Remvloeistof
21-07-23	52.082	Vervanging band
11-11-22	37.893	Vervanging band
29-08-22	34.146	Onderhoudsbeurt
29-11-21	16.869	Onderhoudsbeurt
29-11-21	16.869	Reparatie band(en)
25-11-21	16.500	Vervanging band
09-09-21	11.599	Vervanging band