



Cupra Born: N354VK

Vinnumber:	VSSZZK1ZNP003019	Versionname:	Registratie 2021 Born 150kW/62kWh Copper Edition One automaat
First Registrationdate:	29/12/2021	Fiscalpower:	
Expertise Mileage:	192259	Power Kw:	150
Bodytype:		Body colour	Aurora Blauw
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	769
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	Yes		

Options

Number of keys total	2	Lining Alcantara
GPS		Panoramic roof
Autom climate control		Rear parking sensors
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 45 / 20 / 95 / T / Aluminium	3,3 mm	Michelin	Summer
	Right	215 / 45 / 20 / 95 / T / Aluminium	3,0 mm	Michelin	Summer
Rear	Left	215 / 45 / 20 / 95 / T / Aluminium	1,5 mm	Bridgestone	Summer
	Right	215 / 45 / 20 / 95 / T / Aluminium	1,2 mm	Bridgestone	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Service, Maintenance, Execute



Interior, Dirty, Cleaning




Outer door handle FL, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)




Outer door handle FR, Scratch(es), Repair and paint (complete)



Boot lid covering R, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)



Kenteken	N354VK
Merk Model	Cupra Registratie 2021Born 150kW/62kWh Copper Edition One automaat
Brandstofsoort	Elektrisch
Datum deel1	29-12-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
09-03-26	176.365	Parkeersensor
09-03-26	176.365	Remtrommel
06-11-25	156.493	APK
06-11-25	156.493	Parkeersensor
06-11-25	156.493	Ruitenwisherblad(en) achterzijde
06-11-25	156.493	Ruitenwisherblad(en) voorzijde
06-11-25	156.493	Vervanging band
28-08-24	95.121	Tankklep
28-08-24	95.121	Vervanging band
20-02-23	40.000	Vervanging band
06-01-23	35.167	Vervanging band