MACADAM










CITROÃ‹N C3 SOCIÃ‰TÃ‰: GL-883-EH

Vinnumber:	**VF7SWYHTUNT655426**	Versionname:	**CITROÃ‹N C3 SOCIÃ‰TÃ‰ BlueHDi 100 S&S BVM Feel VF [5P] 6-102CH-5cv (bi-corps VU-)**
First Registrationdate:	**19/12/2022**	Fiscalpower:	
Expertise Mileage:	**116023**	Power Kw:	**75**
Bodytype:	**Berline**	Body colour	**White**
Gearbox:	**MAN 6 VIT**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**2**		
Number head rests	**1**		
Type of rims (mounted)	**Steel**		
Category	**VS**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**1**	Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Cruise Control		Seat cover lining	**Lining Other**
Steering wheel multifunctional			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**185/65/15/92 T**			
	Fr.L.	**Kleber: 80%**	Fr.R.	**Kleber: 85%**
	Re.L.	**Falken: 80%**	Re.R.	**Falken: 75%**

Tyre profile depth FL	**3.0**
Tyre profile depth FR	**2.3**
Tyre profile depth RL	**3.0**
Tyre profile depth RR	**3.4**
Tyre size FL	**185/65 R 15 92 T**
Tyre size FR	**185/65 R 15 92 T**
Tyre size RL	**185/65 R 15 92 T**
Tyre size RR	**185/65 R 15 92 T**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**2479**
Tyre make FR	**2479**
Tyre make RL	**1957074**
Tyre make RR	**1957074**

Assistance equipment

Emergency spare wheel	**Yes**	Jack	**Yes**

Interior, Dirty, Cleaning





Door seal FL, Tear, Replace






Tyre FL, Out of tolerance, Replace




Wheel cover FL, Missing, Replace




Tyre RL, Out of tolerance, Replace




Wheel cover RL, Missing, Replace




Tyre RR, Out of tolerance, Replace




Wheel cover RR, Missing, Replace




Tyre FR, Out of tolerance, Replace




Wheel cover FR, Missing, Replace




Bumper R, Scratch(es), Paint






Bumper R, Scratch(es), Repair and paint (complete)




Bodywork, Not original part, Sticker removal small







ALPHABET

Historique Maintenance

Immatriculation: **GL-883-EH** Date de 1ère immatriculation: **19/12/2022**

Modèle: **Citroen C3 SOCIÉTÉ BlueHDi 100 S&S BVM Feel VF [5P] 6-102CH-5cv (bi-corps VU-)**

Date	Kilométrage	Fournisseur	Descriptif
27/05/2026	104.952	GGE PEZZOTTI MAXEVILLE	RECYCLAGE
			FILTRE CLIM RPLT
			LIQUIDE DE REFROIDISSEMENT RPLT
			REVISION
29/04/2026	103.103	GGE PEZZOTTI MAXEVILLE	DIVERS CARBURANT
			RECYCLAGE
03/04/2026	103.103	GGE PEZZOTTI MAXEVILLE	BV COMPLETE RPLT
			EMBRAYAGE RPLT
			DIVERS
			SOUFFLET DE CARDAN RPLT
10/02/2026	103.103	GGE PEZZOTTI MAXEVILLE	RESERVOIR ADBLUE RPLT
			DIVERS
22/07/2025	94.278	PEZZOTTI	LAMPE RPLT
			RECYCLAGE
			DIVERS SUSPENSION
20/05/2025	87.085	PEZZOTTI	BALAIS ESSUIE GLACE AV
			REVISION
			FILTRE CLIM RPLT
			LIQUIDE DE FREIN
			BALAI ESSUIE GLACE AR
			DISQUES PLAQUETTES AR RPLT
			RECYCLAGE
18/03/2025	85.223	PEZZOTTI	RECYCLAGE
			DIVERS SUSPENSION
02/09/2024	75.223	PEZZOTTI	RECYCLAGE
			REVISION
25/03/2024	61.372	PEZZOTTI	PLAQUETTES AV RPLT
			RECYCLAGE
27/02/2024	61.242	PEZZOTTI	REVISION
			LIQUIDE DE FREIN
			FILTRE CLIM RPLT
			REVISION

Historique Maintenance

Immatriculation: **GL-883-EH** Date de 1ère immatriculation: **19/12/2022**

Modèle: **Citroen C3 SOCIÉTÉ BlueHDi 100 S&S BVM Feel VF [5P] 6-102CH-5cv (bi-corps VU-)**

Date	Kilométrage	Fournisseur	Descriptif
			RECYCLAGE
			FILTRE A AIR RPLT
25/05/2023	32.201	PEZZOTTI	BALAIS ESSUIE GLACE AV
			REVISION
			RECYCLAGE
			FILTRE CLIM RPLT