



Expertise

Protocol number: 46540184
Order No. / Reference: 26584024
Inspection date: 9 Jul 2026

Manufacturer: Mercedes-Benz

Model: GLC-Coupe 300 de 4Matic 9G-TRONIC AMG Line

VIN: W1N2533111G026615



Vehicle details

Manufacturer / Type / Model / Equipment

Mercedes-Benz GLC-Coupe 300 de 4Matic 9G-TRONIC AMG Line

Vehicle Identification number W1N2533111G026615
Mileage (Read) 142,151 km
First registration 1 Dec 2021
Number of holders 1
Next periodical technical inspection 12/2026
(Reption on hand)

Power / Engine displacement 143 kw / 1,950 ccm
Fuel type / Cylinder Hybr.D/E ext.aufl / 4
Gearbox / Number of gears Automatic / 9
Type of drive All-wheel drive
Type of vehicle SUV

Colour / colour code Designo selenitgrau magno
Doors / Seats 5 / 5
Upholstery type Cloth / leather combination
Colour of upholstery Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	183 Tag(e)
Last service on / at	12/2025 at 129,976 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GF753405
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / ASU 00052		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,660 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 105W	Summer tyres on Light alloy	Goodyear	6mm / 6mm
2)	255/50 R19 103V	Summer tyres on Light alloy	Pirelli	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 105V	Winter tyres on Light alloy	Dunlop	5mm / 5mm
2)	235/55 R19 105V	Winter tyres on Light alloy	Dunlop	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Airbag: Kneebag for driver
- Airbag: Windowbags
- Acoustic environmental protection
- AMG pedal assembly made of brushed stainless steel with rubber studs
- Automatic passenger airbag deactivation
- On-board computer
- Diesel particulate filter
- Third brake light in LED technology
- EASY-Pack tailgate with electric operation for opening and closing
- Driving light assistant
- electric parking brake
- Transmission: 9G-TRONIC
- Black fabric headliner
- KEYLESS-GO start function
- Climate: THERMATIC automatic climate control with 2 climate zones
- Communication module (LTE) for the use of Mercedes me connect services
- Charging system: AC on-board charger 7.4 kW
- LED High Performance Headlights
- Steering wheel: Multifunction sports steering wheel in 3-spoke design in black Nappa leather
- Steering column mechanically adjustable in height and length
- Package: Storage
- Package: Chrome
- Upholstery: ARTICO leatherette/DINAMICA microfiber
- Radio accessories: Remote Online
- Tire pressure monitoring system (TPMS)
- Rear view camera
- Seat: Front sports seats
- Seats: i-Size child restraint system on the outer rear seats
- Cruise control
- High-visibility vest for drivers
- Central locking
- Airbag for driver and front passenger
- Airbag: Side airbag for driver and front passenger
- Active Brake Assist
- 4MATIC all-wheel drive
- Anti-lock braking system (ABS)
- ATTENTION ASSIST
- Heated exterior mirrors (left and right), electrically adjustable from inside
- Tachometer
- DYNAMIC SELECT
- EASY-Pack cargo cover (removable)
- Electronic Stability Program (ESP)
- Electric windows (4-way)
- Black floor mats with AMG lettering
- Rear window heated
- Instrument panel and door sills in ARTICO man-made leather
- Instrument cluster with 2 tubular round instruments, 13.97 cm (5.5") multifunction display
- Headrests 5-way
- Charging cable for household socket, 5m, smooth (This charging cable, also called Mode 2 cable, allows you to charge the vehicle battery at the household socket with up to 2.3 kW (230 V, 1-phase, 10 A) and fits sockets of type E/F CEE 7/7.)
- Mercedes-Benz emergency call system
- Navigation accessories: Extended MBUX functions
- Package: AMG Line Exterior (Plug-in Hybrid)
- Package: Interior light
- Radio accessories: Digital radio
- Radio accessories: Touchpad
- Remote Services Plus
- Windscreen wipers with rain sensor
- Seats: Rear seat backrests foldable
- Seats: Front seats electrically adjustable
- Pre-installation for roof rack systems
- Immobiliser
- Decorative elements: black piano lacquer finish/light longitudinally brushed aluminum



Extra equipment

- Airbag: Sidebags in the rear, left and right
- Towbar with ESP trailer stabilization (fully electrically foldable and retractable)
- Head-up display
- KEYLESS-GO
- Paint finish: designo selenite grey magno
- Charging cable for wallbox and public charging stations, 5m, smooth (This charging cable, also called Mode 3 cable, allows you to charge the vehicle battery at the wallbox or at public charging stations with up to 7.4 kW (Type 2, 3-phase, 20 A).)
- Package: Advanced Light (LED High Performance headlights and adaptive LED taillights, Adaptive Highbeam Assist)
- Package: AIR-BALANCE (including ionization, improved air filtration and fragrance)
- Package: High End Assistance (Mirror package: Electrically folding exterior mirrors, lowering right exterior mirror, automatic dimming function; Driving assistance package: Active Distance Assist DISTRONIC, Active Steering Assist, Active Brake Assist, Evasive Steering Assist, Active Lane Keeping Assist, Active Blind Spot Assist, PRE-SAFE PLUS)
- Package: High-end infotainment (Media display with touch controls, smartphone integration: Apple CarPlay and Android Auto, connectivity package, navigation, traffic sign assistant: thanks to intelligent linking of camera and map data, it can recognize not only speed limits, no-overtaking zones and their cancellation, but also fully digital instrument display, wireless charging system for mobile devices in the storage compartment)
- Remote and Charging Services Plus (The Remote and Charging Services Plus package connects you to the vehicle. You can locate it if desired and remotely control selected functions. With Mercedes me Charge, you can charge your vehicle at many public charging stations with maximum cost transparency. You only need to register once and receive a single, centralized bill.)
- Heated windshield washer system
- Heat and sound insulating acoustic glass (The heat and sound insulating acoustic glass for the front side windows offers you greater noise comfort.)
- Ambient lighting (Design the interior according to your personal preference or current mood. With a total of 64 colors, the ambient lighting offers almost unlimited possibilities for lighting design and has the right color for every situation. Illuminated door sills on the driver and passenger sides.)
- Discount code for the removal of the wireless charging system
- Navigation accessories: Pre-installation for Live Traffic Information (With Live Traffic Information, your navigation system receives real-time traffic data and optimizes dynamic route guidance. Thanks to precise and up-to-date information on traffic jams, stop-and-go traffic, and more, you are supported in reducing travel times.)
- Package: Business (for plug-in hybrid vehicles) (Advanced Parking Package: Active Parking Assist PARKTRONIC with reversing camera; Advanced Infotainment Package: Media display with touch operation, smartphone integration - Apple CarPlay and Android Auto, connectivity package navigation, traffic sign assist; Comfort Package: Heated seats for driver and front passenger, seat comfort package - electric and manual adjustment options for the front seats; Public Charging Package)
- Package: High End Park (Parking package with 360° camera, Active Parking Assist with PARKTRONIC)
- Package: Comfort (Seat heating for driver and front passenger, electric and manual adjustment options for driver and front passenger seats, electro-pneumatic 4-way lumbar support and lateral support adjustment with control element on the seat, electric seat cushion tilt adjustment, electric height adjustment, electric backrest adjustment, mechanical seat cushion depth adjustment by 6 cm with leg rest pad, mechanical longitudinal adjustment, mechanical headrest adjustment)
- Wheels: 48.3 cm (19") AMG light-alloy wheels, 4-piece set in 5-twin-spoke design (high-gloss black painted and polished with front axle 235/55 R 19 on 8 J x 19 ET 38 and rear axle 255/50 R 19 on 9 J x 19 ET 20)
- Electric sunroof (glass design with anti-pinch protection).
- Decorative elements: open-pore black ash wood / light longitudinally brushed aluminum

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Side panel - rear left side	Mudguard - rear left side - Scratch(es) - Smart repair
2	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
3	Wing mirror - left side	Cap - Scratch(es) - Replace
4	Door - rear left side	Door - Dent / paintcoat damage - Paint
5	Door - front right side	Door - Scratch(es) - Paint
6	Door - front left side	Door - Scratch(es) - Paint
7	Front bumper	Front bumper (Sandstrahleffekt) - Stone chips - Paint
8	Boot lid / rear door	Boot lid - Scratch(es) - Paint
9	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	A-pillar - left side - Stone chips - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.



Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Der beiliegende Winterradsatz ist kein Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.




Figure 35: Misc.



Figure 36: Misc.



Damage 1: Side panel - rear left side: Mudguard - rear left side - Scratch(es) - Smart repair



Damage 1: Side panel - rear left side: Mudguard - rear left side - Scratch(es) - Smart repair



Damage 2: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 2: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 3: Wing mirror - left side: Cap - Scratch(es) - Replace



Damage 3: Wing mirror - left side: Cap - Scratch(es) - Replace



Damage 3: Wing mirror - left side: Cap - Scratch(es) - Replace




Damage 4: Door - rear left side: Door - Dent / paintcoat damage - Paint



Damage 4: Door - rear left side: Door - Dent / paintcoat damage - Paint



Damage 4: Door - rear left side: Door - Dent / paintcoat damage - Paint



Damage 4: Door - rear left side: Door - Dent / paintcoat damage - Paint



Damage 5: Door - front right side: Door - Scratch(es) - Paint



Damage 5: Door - front right side: Door - Scratch(es) - Paint




Damage 5: Door - front right side: Door - Scratch(es) - Paint



Damage 6: Door - front left side: Door - Scratch(es) - Paint



Damage 6: Door - front left side: Door - Scratch(es) - Paint



Damage 6: Door - front left side: Door - Scratch(es) - Paint



Damage 7: Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint



Damage 7: Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint



Damage 7: Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint



Damage 8: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 8: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 9: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 9: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 9: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Wear and tear 1: Body: A-pillar - left side - Stone chips - No deduction



Wear and tear 1: Body: A-pillar - left side - Stone chips - No deduction



Wear and tear 2: Vehicle glazing: Windscreen - Stone chips - No deduction



Wear and tear 2: Vehicle glazing: Windscreen - Stone chips - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1N2533111G026615

Hersteller / Modell: MERCEDES-BENZ MERCEDES-BENZ GLC-Coupe 300 de 4Matic
9G-TRONIC AMG Line

Datum	KM-Stand	Beschreibung
16.04.2026	136.108	Bremsscheiben vorne
15.01.2026	129.976	Systemtest/Eigendiagnose
23.12.2025	129.976	Bremsscheiben hinten; Regelwartungsdienst
28.03.2025	105.757	Regelwartungsdienst; Systemtest/Eigendiagnose
06.12.2024	0	HU + AU
28.05.2024	79.893	Regelwartungsdienst
01.09.2023	54.808	Regelwartungsdienst
21.10.2022	26.440	Regelwartungsdienst