



BMW 3 BERLINE:

Vinnumber:	WBA5V31040FK77221	Versionname:	318da (100 kW)
First Registrationdate:	13/01/2021	Fiscalpower:	
Expertise Mileage:	154244	Power Kw:	100
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	4215
Fueltype:	Hybrid Diesel		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Front parking sensors:	
Cruise Control:		Rear parking sensors:	
Steering wheel multifunctional:		Type of Tow bar:	No Tow bar
Seats F heated:			
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Tyres

205/60/16/96 H				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 2 mm	Re.R.	Michelin: 2 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				2.0
Tyre profile depth RR				2.0
Tyre size FL				205/60 R 16 96 H
Tyre size FR				205/60 R 16 96 H
Tyre size RL				205/60 R 16 96 H
Tyre size RR				205/60 R 16 96 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Number of charging cables (normal):	0
Number of charging cables (rapid charge):	0

Total cost ex VAT:	175,04
Interior, Dirty, Cleaning:	175,04



Windscreen, Stone chip(s), Windscreen repair 0,00



Bumper F, Scratch(es), Repair and paint (complete) 0,00



Door FL, Scratch(es), Acceptable 0,00



Door RL, Scratch(es), Acceptable 0,00



Alloy rim RL polished, Chemical polution, Acceptable 0,00



Bumper R, Dent(s) and scratch(es), Repair and paint (complete) 0,00



Wheel aperture RR, Dent(s) and scratch(es), Spot repair 0,00



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)

0,00



Door RR, Dent(s) and scratch(es), Repair and paint (complete)

0,00



Door FR, Scratch(es), Acceptable

0,00



Alloy rim FR, Scratch(es), Acceptable

0,00



Wing FR, Scratch(es), Acceptable

0,00



Central pillar R, Scratch(es), Acceptable

0,00



Roof, Dent(s) and scratch(es), Repair and paint (complete)

0,00



