



IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	BMW
Model / version:	X1 DIESEL - 2019
Vin:	WBA31AC0305T24409
Plate:	2ACH920
Mileage:	112014
First registration:	17/02/2021
Color:	Saphirblack





ADDITIONAL INFORMATION


Category:
Transmission:
Interior color:
Metallic paint: ?
Type of lining:
Board computer reset: ?

DOCUMENTS

Certificate of conformity: ✓
Registration certificate: ✓
Registration certificate 2: ✓
Insurance certificate: ?
Maintenance book:
Number of keys: 2
Original key: ✓

PICTURES





VIN INFORMATION

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	×	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	×
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			Winter		?
Front right	5 mm			Winter		?
Rear left	5 mm			Winter		?
Rear right	5 mm			Winter		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
2	Door RL	Dent(s) and scratch(es)
3	Tyre repair kit	Missing
4	Step R	Scratch(es)
5	Outside rear-view mirror housing R	Scratch(es)

Total: 4

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
1	Bodywork	Damaged	✓	✗	✗

Total: 1

DAMAGES DETAILS


2 - Door RL - Dent(s) and scratch(es)



3 - Tyre repair kit - Missing



4 - Step R - Scratch(es)



5 - Outside rear-view mirror housing R - Scratch(es)



1 - Bodywork - Damaged - Renta®



SIGNATURE
