



## OPEL Corsa: 4825-MBB

Vinnumber:	<b>VXKUPHNEKN4334160</b>	Versionname:	<b>1.2T XHL 74kW (100CV) Edition berlina con portón</b>
First Registrationdate:	<b>6/09/2022</b>	Fiscalpower:	<b>74kW 5P manual</b>
Expertise Mileage:	<b>65015</b>	Power Kw:	
Bodytype:	<b>Berline</b>	Body colour:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:			
Fueltype:	<b>Petrol</b>		
Engine functioning:	<b>Yes</b>		
Battery functioning:	<b>Yes</b>		
Vehicle running:	<b>Yes</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>No</b>		

## Options

Number of keys total:	<b>2</b>	Luggage cover:	
Number keys remote:	<b>1</b>		
GPS big screen color:			
Windows electric F:			
Windows electric R:			
Cruise Control:			
Steering wheel multifunctional:			
Radio multimedia:			
Type of climate control:	<b>Manual climate control</b>		

## Tyres

195/55/16/87 H				
Summer tyres:	Fr.L.	<b>Nexen: 6 mm</b>	Fr.R.	<b>Nexen: 6 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>
Tyre profile depth FL				<b>6.0</b>
Tyre profile depth FR				<b>6.0</b>
Tyre profile depth RL				<b>4.0</b>
Tyre profile depth RR				<b>4.0</b>
Tyre size FL				<b>195/55 R 16 87 H</b>
Tyre size FR				<b>195/55 R 16 87 H</b>
Tyre size RL				<b>195/55 R 16 87 H</b>
Tyre size RR				<b>195/55 R 16 87 H</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>1957072</b>
Tyre make FR				<b>1957072</b>
Tyre make RL				<b>256</b>
Tyre make RR				<b>256</b>

## Assistance equipment

Repair kit:	<b>Yes</b>
-------------	------------

Registration document, Missing, Repair/replace (lump sum)



Door panel FL, Scratch(es), Replace



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Bonnet, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check



