



Volkswagen Golf (UKL): 2EKM348

Vinnumber:	WVWZZZCD1PW535748	Versionname:	Golf VIII Variant Life Business 1.0TSi 110pk/cv 5p
First Registrationdate:	2/11/2023	Fiscalpower:	
Expertise Mileage:	73377	Power Kw:	81
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	plus 24400 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/55/16/94 V			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/55 R 16 94 V
Tyre size FR				205/55 R 16 94 V
Tyre size RL				205/55 R 16 94 V
Tyre size RR				205/55 R 16 94 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				256
Tyre make FR				256
Tyre make RL				265
Tyre make RR				265

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Instrument panel, complete, Not functioning (well), Check



Interior, Smell, Ozone treatment



Door panel RR, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Kenteken	2EKM348
Merk Model	Volkswagen Golf VIII Variant Life Business 1.0TSi 110pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	11/2/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
5/6/26	67,764	bougie	Vervangen
5/6/26	67,764	klein materiaal	
5/6/26	67,764	luchtfilter interieur	Vervangen
5/6/26	67,764	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
5/6/26	67,764	remvloeistof	Vervangen
5/6/26	67,764	ruitenswisserrubber achter	Vervangen
5/6/26	67,764	ruitenswisserrubber vooraan	Vervangen
5/6/26	67,764	ruitenswisservloeistof	Bijvullen/-laden
9/17/25	50,765	controle niveaus	Uitvoeren
9/17/25	50,765	luchtfilter	Vervangen
9/17/25	50,765	luchtfilter interieur	Vervangen
9/17/25	50,765	remblokken vooraan	Reinigen
9/17/25	50,765	remvloeistof	Vervangen
3/10/25	36,917	batterij	Vervangen
3/10/25	36,917	Inspectie met olie vervanging (vast in	Uitvoeren
3/10/25	36,917	klein materiaal	
3/10/25	36,917	ruitenswisserrubber achter	Vervangen
3/10/25	36,917	ruitenswisserrubber vooraan	Vervangen