

MACDAM

Opel * Vivaro '19

Vehicle information


Make:	Opel	License:	
Gearbox:	MAN 6 VIT	Body color:	
Model:	* Vivaro '19	VIN:	VXEVBYPHRMPZ043390
Fuel type:	Diesel	Power:	75 kW
Version:	Vivaro L2 1.5D 100	First registration	30/06/2023
Mileage:	274236 km	N° of doors:	

Damage summary

Front	2
Interior	2
Roof & others	1

Commercial pictures





Options according to the inspector

Central consol F	Yes	GPS	Yes	Radio multimedia	Yes
Telephone equipment	Yes				

Damages

Bodywork

Not original part
Remove lettering
Roof & others



Bumper FM

Stone chip(s)
Repair and paint (complete)
Front



Interior

Stain
Cleaning
Interior




User's manual

Missing
Replace
Interior

Windscreen

Stone chip(s)
Windscreen repair
Front



Tyres	
	Front Left
	Summer
	215/65/16/109/T
	Michelin
	7.7 mm
	Front Right
	Summer
	215/65/16/109/T
	Michelin
	7.9 mm
	Rear Left
	Summer
	215/65/16/109/T
	Michelin
	7.9 mm
	Rear Right
	Summer
	215/65/16/109/T
	Michelin
	7.8 mm

Checks			
CO2 Emission	170	Digital maintenance	N/A
GPS storage	Yes	Luggage cover	N/A
Number head rests	3	Number of keys total	2
Reset to factory settings	Yes, vehicle is reset to factory settings	Service book	No
User's manual	No		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.