



PEUGEOT PARTNER:

Vinnumber:	VR3EFYHWCKJ769300	Versionname:	1.5 BHD L1 Light 55kW Premium
First Registrationdate:	9/12/2019	Fiscalpower:	
Expertise Mileage:	129648	Power Kw:	55
Bodytype:		Body colour:	White
Gearbox:	MAN 5 VIT	Type of rims (mounted):	Steel
Transmission:		Parking lot:	1233
Fueltype:	Diesel		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Type of headlighting:	Headlighting Halogen	Rear parking sensors:	
Type of GPS:	GPS base	Type of Tow bar:	Tow bar fixed
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		

Limited Technical Inspection

Tyres

195/65/15/95 T				
Summer tyres:	Fr.L.	Other: 3 mm	Fr.R.	Other: 3 mm
	Re.L.	Other: 2 mm	Re.R.	Other: 2 mm
Tyre profile depth FL	3.0			
Tyre profile depth FR	3.0			
Tyre profile depth RL	2.0			
Tyre profile depth RR	2.0			
Tyre size FL	195/65 R 15 95 T			
Tyre size FR	195/65 R 15 95 T			
Tyre size RL	195/65 R 15 95 T			
Tyre size RR	195/65 R 15 95 T			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	263			
Tyre make FR	263			
Tyre make RL	263			
Tyre make RR	263			

Assistance equipment

Emergency spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	1247,91
Interior, Damaged, Acceptable:	0,00





Instrument panel, complete, Not functioning (well), Check	0,00
---	------



Air vent L, Broken, Replace	56,65
-----------------------------	-------



Instrument panel, complete, Crack, Forfeit	274,50
--	--------



Windscreen, Stone chip(s), Replace	407,12
------------------------------------	--------




Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------



Step L, Scratch(es), Repair and paint (complete)	161,81
--	--------



Wing RL, Dent(s), Acceptable	0,00
------------------------------	------



Wing FL, Dent(s), Acceptable	0,00
------------------------------	------



Boot door panel RL, Dent(s), Acceptable	0,00
---	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Steel rim FR, Scratch(es), Acceptable	0,00
---------------------------------------	------



A-pillar right, Bad repair, Check	0,00
-----------------------------------	------



Outer sill R, Dent(s), Repair and paint (complete)	347,83
--	--------

