



**Ford Mustang: L945JX**

Vinnumber:	<b>WF0TK1EM0MMA14388</b>	Versionname:	<b>Mustang Mach-E 190kW/ 75,7kWh RWD automaat</b>
First Registrationdate:	<b>28/06/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>125343</b>	Power Kw:	<b>190</b>
Bodytype:		Body colour:	<b>Premium Metaallak: Carbonized Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Electric</b>	Parking lot:	<b>584</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>No</b>		

**Options**

Number of keys total	<b>2</b>	Lining leather
GPS		Rear parking sensors
Autom climate control		Rear view camera
Radio multimedia		

**Tyres**

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 60 / 18 / 104 / V / Aluminium	4,7 mm	Continental	Winter
	Right	225 / 60 / 18 / 104 / V / Aluminium	5,5 mm	Continental	Winter
Rear	Left	225 / 60 / 18 / 104 / V / Aluminium	5,7 mm	Continental	Winter
	Right	225 / 60 / 18 / 104 / V / Aluminium	5,2 mm	Continental	Winter

**Assistance equipment**

Number of charging cables (normal)	<b>1</b>
Number of charging cables (rapid charge)	<b>1</b>

**Door FL, Dent(s), Repair and paint (complete)**



**Door RL, Scratch(es), Repair and paint (complete)**



**Bonnet, Stone chip(s), Repair and paint (complete)**



**Wheel arch cover RR, Scratch(es), Replace**



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Boot cover, Missing, Replace



Bumper R, Scratch(es), Repair and paint (complete)



<b>Kenteken</b>	L945JX
<b>Merk Model</b>	Ford Mustang Mach-E 198kW/ 75,7kWh RWD automatisch
<b>Brandstofsoort</b>	Elektrisch
<b>Datum deel1</b>	28-06-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
26-05-25	107.675	APK
26-05-25	107.675	Onderhoudsbeurt
26-05-25	107.675	Remvloeistof
26-05-25	107.675	Vervanging band
11-04-25	107.675	Aandrijfas
11-04-25	107.675	Wiellager achter
02-06-23	52.911	Onderhoudsbeurt
02-06-23	52.911	Remvloeistof