DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	VR3FRHNS4 RY574333	Registration date	12/07/2024	Exterior Color	Unknown
Brand	PEUGEOT	Licence Plate	HB-DO 911	Odometer	41 613 km
Model	308 PureTech 130 EAT8 GT SW				

Inspection Details

Arrival Date	17/08/2026	Inspection ID	7117153	Inspection date	18/08/2026
Assign Date	17/08/2026	Fleet owner	Leasys Privat Leasing	Inspection loc.	Leasys Hubmotion Gifhorn

















Generic equipment

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓
Radio user manual	✓


Technical Document

User manual	✓
Warranty booklet	✓
Log books	✓
Spare key	✓
Key	✓
Service	✗

Tyres

Michelin 225/40/18 Y Summer 5.0 mm

Michelin 225/40/18 Y Summer 5.0 mm



Michelin 225/40/18 Y Summer 5.0 mm

Michelin 225/40/18 Y Summer 5.0 mm



Exception / Damage

1



Part	Service	Repair Time	-	Part Cost	250.00€
Position	-	Repair Cost	-	Gross Cost	250.00€
Damages	Missing	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**250.00€**

DEKRA

DEKRA Automotive Solutions

Appraisal Report

2



Part	Bumper	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Scratched	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

3



Part	Bonnet	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Scratched	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

4



Part	Windscreen	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

5



Part	Engine soundproofing	Repair Time	0.20	Part Cost	85.66€
Position	Front	Repair Cost	28.00€	Gross Cost	113.66€
Damages	Cut	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	- 17.05
Repair mode	Replace	Flat Rate	-	**Net Cost**	**96.61€**

Summary Inspection

Gross Price	363.66€	Depreciation	-17.05€	Net Price	346.61€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	140.00€	0.20	28.00€	15.00 %	-4.20€	23.80€
Paintwork	0.00€	0.00	0.00€	-	-	0.00€
Paint preparation	0.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	335.66€	3.83 %	-12.85€	322.81€
Flat Rate	-250.00€	-	-	-250.00€