DEKRA

DEKRA Automotive Solutions


Appraisal Report

Vehicle details

VIN	W0VZRHNS8 R6035438	Registration date	16/10/2024	Exterior Color	Unknown
Brand	OPEL	Licence Plate	BI-MC 460	Odometer	-
Model	GRANDLAND 1.2 Turbo 96kW GS Auto				

Inspection Details

Arrival Date	21/07/2026	Inspection ID	7087360	Inspection date	23/07/2026
Assign Date	22/07/2026	Fleet owner	Leasys Privat Leasing	Inspection loc.	Leasys SLC Essen



Generic equipment

Removable element


Technical Document

Warranty booklet	✔
Key	✔
Spare key	✖

Tyres

Goodyear 225/55/18 V All seasons 5.0 mm

Goodyear 225/55/18 V All seasons 5.0 mm



Goodyear 225/55/18 V All seasons 6.0 mm

Goodyear 225/55/18 V All seasons 6.0 mm

Exception / Damage

1



Part	Spare key	Repair Time	0.50	Part Cost	287.88€
Position	-	Repair Cost	70.00€	Gross Cost	357.88€
Damages	Missing	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**357.88€**

DEKRA

DEKRA Automotive Solutions

Appraisal Report

2



Part	Third-Party Expertise	Repair Time	-	Part Cost	-
Position	-	Repair Cost	-	Gross Cost	-
Damages	Missing	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	-

Comments

Km Stand nicht ablesbar , Tacho ohne Funktion
Heckklappe ohne Funktion, fzg nicht Fahrbereit, Verdeckte Schäden möglich, Fzg stark verschmutzt

Summary Inspection

Gross Price	357.88€	Depreciation	-	Net Price	357.88€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	140.00€	0.50	70.00€	-	-	70.00€
Paintwork	0.00€	0.00	0.00€	-	-	0.00€
Paint preparation	0.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	287.88€	-	-	287.88€
Flat Rate	-357.88€	-	-	-357.88€