MACADAM



VOLVO XC90: 4294-MWK

Vinnumber:	**YV1LFH7V7S1304705**	Versionname:	**2.0 T8 AWD Core Recharge Auto todoterreno 335kW 5P automática**
First Registrationdate:	**18/11/2024**	Fiscalpower:	
Expertise Mileage:	**30736**	Power Kw:	
Bodytype:	**Off-road**	Body colour	**Black**
Gearbox:	**Automatic**	Type of rims (mounted)	**Aluminium**
Transmission:			
Fueltype:	**Hybrid**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**7**		
Number head rests	**7**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**No**		

Options

Number of keys total	**2**	Seats electric F L	
Number keys remote	**2**	Seats electric F R	
GPS big screen color		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Headlight sprinkler	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Steering wheel leather		Roof bar alu	
Seats F heated			
Radio multimedia			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**235/55/19/105 V**			
	Fr.L.	**Goodyear: 7 mm**	Fr.R.	**Goodyear: 7 mm**
	Re.L.	**Goodyear: 7 mm**	Re.R.	**Goodyear: 7 mm**

Tyre profile depth FL	**7.0**
Tyre profile depth FR	**7.0**
Tyre profile depth RL	**7.0**
Tyre profile depth RR	**7.0**
Tyre size FL	**235/55 R 19 105 V**
Tyre size FR	**235/55 R 19 105 V**
Tyre size RL	**235/55 R 19 105 V**
Tyre size RR	**235/55 R 19 105 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Repair kit	**Yes**
Number of charging cables (normal)	**1**
Number of charging cables (rapid charge)	**1**

User's manual, Missing, Repair/replace (lump sum)




Registration document, Missing, Repair/replace (lump sum)




Air vent L, Damaged, Replace




Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)




Door FL, Scratch(es), Acceptable




Door FR, Scratch(es), Repair and paint (complete)




Door RR, Stone chip(s), Acceptable




Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)




Bumper R, Scratch(es), Repair and paint (complete)




Tailgate / Boot, Dent(s), Repair and paint (complete)





Tyres, No damage, Check



ALPHABET

Datos del vehículo

Marca	VOLVO	Matrícula	4294-MWK
Modelo	XC90	VIN	YV1LFH7V7S1304705
Versión	2.0 T8 AWD Core Recharge Auto todoterreno 335kW 5P automática		

Histórico

Fecha	Descripción	Kilómetros	Taller
18/08/2025	Luna parabrisas	0	RALARSA HOLDING S.L.
25/11/2025	, bola automatica, , Puerta delantera izquierda, Puerta trasera izquierda, Aleta delantera izquierda, Aleta trasera izquierda, Puerta delantera derecha, Puerta trasera derecha, Aleta delantera derecha, Aleta trasera derecha, Paragolpes trasero, Paragolpes delantero, Capó	1	TALLERES DECAMOVIL, S.L.UNIP.
07/11/2025	Aceite motor - Precio litro pactado, Arandela / tapón cárter, Filtro aceite, Filtro antipolen, Rellenar niveles fabricante, Serv inspección 1º año, Sustituir Filtro antipolen, Tasa de gestión de aceites usados	21326	BATTICALOA INVERSIONES S.L.
23/02/2026	Alineado sencillo, Ecotasa - N2, Goodyear / 581668 235/55X19 GYEAR.EFFC.2 SUV105V, Sustitucion y kit de montaje	27173	SADECO S.A.
06/03/2026	Llanta/neumático trasero izquierdo, solporte amortiusdores y amortiguadores, ballesta | Ecotasa - N2, Goodyear / 581668 235/55X19 GYEAR.EFFC.2 SUV105V, Sustitucion y kit de montaje	123456	SALADAR CENTER S.L.

Fecha	Descripción	Kilómetros	Taller