



CITROËN BERLINGO: FK-545-GN

Vinnumber:	VR7EFYHYCKN541703	Versionname:	CITROËN BERLINGO M 650kg BlueHDi 100 S&S
First Registrationdate:	23/09/2019		BVM Driver VU [4P] bvm 5-100CH-5cv
Expertise Mileage:	123703		(fourgonnettesimple cabine)
Bodytype:	Transporter	Fiscalpower:	
Gearbox:	MAN 5 VIT	Power Kw:	73
Transmission:	Front	Body colour:	White
Fueltype:	Diesel	Paint type:	Opaque
Engine functioning:	Yes	Interior colour:	Black
Battery functioning:	Yes	Type of rims (mounted):	Steel
Vehicle running:	Yes	Dashboard color:	Black
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	2	Radio	
Number keys remote	1	Front parking sensors	
GPS big screen color		Rear parking sensors	
GPS storage		Sliding door right-side	
GPS storage	HD	Rear view camera	
Windows electric F		Seat cover lining	Lining Other
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Manual climate control		

Tyres

	195/65/15/95 H			
Summer tyres:	Fr.L.	Kleber: 45%	Fr.R.	Kleber: 60%
	Re.L.	Kleber: 30%	Re.R.	Kleber: 35%
Tyre profile depth FL				5.4
Tyre profile depth FR				4.2
Tyre profile depth RL				6.1
Tyre profile depth RR				5.9
Tyre size FL				195/65 R 15 95 H
Tyre size FR				195/65 R 15 95 H
Tyre size RL				195/65 R 15 95 H
Tyre size RR				195/65 R 15 95 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				2479
Tyre make FR				2479
Tyre make RL				2479
Tyre make RR				2479

Assistance equipment

Spare wheel	Yes	Jack	Yes
Malfunction indicator, Blinking, Check			



Seat cover FR, Stain, Cleaning



Seat cover FL, Tear, Replace



Backrest cover FL, Tear, Replace



Inner door sill FL, Scratch(es), Paint



Roof pillar L, Dent(s), Repair and paint (complete)



Bonnet, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Number plate F, Deformed / Strained, Repair/replace (lump sum)



Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Missing, Replace



Wing FR, Dent(s), Repair and paint (complete)



Rear light L, Broken, Replace



Historique Maintenance

Immatriculation: **FK-545-GN** Date de 1ère immatriculation: **23/09/2019**

Modèle: **Citroen BERLINGO M 650kg BlueHDi 100 S&S BVM Driver VU [4P] bvm 5-100CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
16/01/2025	103.230	EUROMASTER FRANCE	REPLACEMENT PNEUS 4 SAISONS
03/09/2024	93.911	DEKRA AUTOMOTIVE S.A	ANTIPOLLUTION
19/06/2026	80.484	VETILLE AUTOMOBILES	ADBLUE
			DISQUES PLAQUETTES AV RPLT
			CLE TELECOMMANDE DE DEMARRAGE RPLT
26/06/2024	80.484	VETILLE AUTOMOBILES	DISQUES PLAQUETTES AR RPLT
02/01/2024	80.484	VETILLE AUTOMOBILES	FAP RPLT
22/09/2023	71.952	VETILLE AUTOMOBILES	PLAQUETTES AV RPLT
			BALAIS ESSUIE GLACE AV
			REVISION
			LIQUIDE DE FREIN
			DIVERS CLIM
22/09/2023	71.952	VETILLE AUTOMOBILES	CONTROLE TECHNIQUE
23/05/2023	61.719	VETILLE AUTOMOBILES	DOSSIER ASSISTANCE
			TELECHARGEMENT CALCULATEUR
02/03/2023	58.170	EUROMASTER FRANCE	REPLACEMENT PNEUS ETE
			REPARATION DE ROUE
15/11/2022	45.585	EUROMASTER FRANCE	REPLACEMENT PNEUS ETE
13/07/2022	39.880	VETILLE AUTOMOBILES	REVISION ET CLIM ET AIR ET CARBURANT
			REVISION ET CLIM ET AIR ET CARBURANT
			BALAIS ESSUIE GLACE AV
			REVISION ET CLIM ET AIR ET CARBURANT
			REVISION ET CLIM ET AIR ET CARBURANT
03/02/2022	27.710	EUROMASTER FRANCE	REPARATION DE ROUE