




Peugeot 308:				
Vinnumber:	VR3FRHNSTPY541779	Versionname:		
First Registrationdate:	28/04/2023	Fiscalpower:		
Expertise Mileage:	103289	Power Kw:	96	
Bodytype:		Body colour	Green	
Gearbox:	Automatic	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	3232	
Fueltype:	Petrol			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Options				
Number of keys total	2	Seats electric F L		
Cruise Control		Sun Roof electric		
Steering wheel multifunctional		Panoramic roof		
Seats F heated		Luggage cover		
Radio multimedia		Front parking sensors		
Type of headlighting	Headlighting LED	Rear parking sensors		
Type of GPS	GPS big screen color	Type of Tow bar	No Tow bar	
Type of Lining	Lining semi-artificial leather			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Tyres				
Summer tyres:	225/40/18/92 H			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/40 R 18 92 H
Tyre size FR				225/40 R 18 92 H
Tyre size RL				225/40 R 18 92 H
Tyre size RR				225/40 R 18 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261
Assistance equipment				
Repair kit	Yes	Compressor		Yes
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT				1913,66
Bonnet, Chemical polution, Acceptable				0,00



Alloy rim RL polished, Rust, Acceptable	0,00
---	------




Door FL, Dent(s) and scratch(es), Repair and paint (complete)	445,79
---	--------



Alloy rim FL polished, Scratch(es), Repair and paint (complete)	204,21
---	--------



Tyre FL, Tear, Replace	180,98
------------------------	--------



Alloy rim FR polished, Scratch(es), Repair and paint (complete)	204,21
---	--------



Alloy rim RR polished, Scratch(es), Repair and paint (complete)	204,21
---	--------



Roof, Chemical polution, Repair and paint (complete)	674,26
--	--------

