APPRAISAL REPORT



VEHICLE IDENTIFICATION

Driver name:	ASSE I
Make:	MERCEDES
Model / version:	CLASS GLB (X247)
Wine:	W1N2476871W048282
Plate:	1YMF417
Mileage:	169828
First registration:	06/10/2020
Color:	ZILV IRIDIUM

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book	
Number of keys:	2
Original key:	✓

PICTURES





































WINE INFORMATION

Radio	Touch screen	Automatic transmission
7 reports	Halogen spotlights	LED daytime running lights
Advantage Equipment	Material: alloy	Reference letter (J)
Front diameter 17	Rear diameter 17	Front width 6.5
Rear width 6.5	Front diameter 17	Rear diameter 17
Front height 65	Rear height 65	Forward speed index V
Rear speed index V	Front width 215	Rear width 215
Air Conditioning	Air conditioning refrigerant 1234YF	Illuminated driver's sun visor
Illuminated passenger sun visor	Carbon interior finish	Metallic varnished
Hard varnish (to avoid displaying group 1700)	Electrically adjustable left-side mirror	Electrically adjustable right-side mirror
Automatic day/night left rearview mirror	Electrically folding mirrors	Left rearview mirror with GPS antenna
Automatic day/night interior rearview mirror	Heated front left seat	Heated front seats
Height-adjustable front left seat	Height-adjustable front seats	Fabric and imitation leather trim
Leather steering wheel	Sports steering wheel	Volant multifonction
Aide au stationnement avant	Aide au stationnement arrière	Assistance au parking
Caméra arrière de recul	Régulateur automatique de la distance	Affichage lecture des panneaux de signalisation
Appel de secours	Attelage avec boule amovible	Fixotoit aluminium
Airbag passager désactivable	Airbag de genoux	Ceintures de sécurité avant à enrouleur

Prétensionneurs de ceintures avant
Programme électronique de stabilité ESP
Contrôle pression des pneus
modifications techniques AEJ 19/2

tuner DAB
dossiers ar rabattables

pare-soleil avec fonction spéciale
écran de radiateur supérieur
management des cylindres
Tirefit
extincteur

Témoin d'oubli de ceinture arrière
Assistant maintien de la voie
palettes de sélection au volant
train ar multi-bras

Display combiné
support boissons double

module de communication
échappement avec OPF generation
DYNAMIC SELECT
évaluation des pays Euro NCAP
prise de courant 12 V dans compartiment chargement

Protection piéton
Avertisseur d'angle mort
depuis 02.20
année de modifications 2019 (modèle 2020)

Display central 10,25"
vide-poches dans console centrale avec pare-soleil à enrouleur

écran de radiateur
pack compartiment chargement
suspension confort
compresseur de climatisation variable
site de production Mexico

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
GPS:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Heated front seats:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlight type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Kind	Rims	Runflat
Front left	2 mm	Pirelli	215651799v	Summer	Aluminum	×
Front right	2 mm	Pirelli	215651799v	Summer	Aluminum	×
Rear left	2 mm	Pirelli	215651799v	Summer	Aluminum	×
Rear right	2 mm	Pirelli	215651799v	Summer	Aluminum	×

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Rental	Damage type
		No damages present

ACCEPTABLE / NOT TO BE INVOICED

#	Rental	Damage type	Renta®	Repaired	Already invoiced
1	Cap	Teeth)	✓	×	×
2	Alloy rim FL		✓	×	×

Total: 2

DAMAGE DETAILS

1 - Cap - Tooth(s) - Renta®



2 - Alloy rim FL - Renta®





SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

27/10/2026 11:19



Customer

27/10/2026 11:19

Useless