APPRAISAL REPORT



VEHICLE IDENTIFICATION

Driver name:	ASSE I
Make:	FORD
Model / version:	KUGA
Wine:	WF0FXXWPMFRG09616
Plate:	2FQB611
Mileage:	29857
First registration:	08/07/2024
Color:	SOLAR SILVER

ADDITIONAL INFORMATION


Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS


Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book	
Number of keys:	2
Original key:	✓

PICTURES



















































WINE INFORMATION

10 Speakers	Manual transmission	6 reports
Leather gear shift knob	Front-wheel drive	Automatic headlights
LED spotlights	Body-colored side protection strips	Rear spoiler
Front diameter 18	Rear diameter 18	Front height 60
Rear height 60	Forward speed index H	Rear speed rating H
Front width 225	Rear width 225	Flat steel spare wheel
Automatic climate control	Air conditioning refrigerant 1234YF	Rear center armrest
Essence	1497 cm3	1.50 liters
88 kW	120 hp	Euro 6.2
Varnished mica	Electric handbrake	Heated front left seat
Heated front seats	Front seats with memory settings	Sport suspension
Sports steering wheel	Heated steering wheel	Front parking assistance
Rear parking assistance	Parking assistance	Automatic distance control
Electrically operated trunk opening	Heated windshield	Dark tinted rear window
Laminated front door windows	Dark tinted rear door windows	Dark tinted quarter windows
rain sensor windshield wiper	Fixotoit black	Blind spot warning system
since 02.24 RR/RA/RG (Facelift)	Child safety electrical	Chrome electric/heated/folding/memory mirrors/pitch lighting
wireless charging system for GSM	digital radio	combined instrument cluster with 12.3" digital monitor
66 series (ST-Line X)	folding tow hitch	LED interior lighting

360° driving camera
aluminum pedals
honeycomb grille with black surround
“ECO-Innovation” alternator
door edge protection
brake calipers painted red
"Start & Stop" System

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
GPS:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Heated front seats:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlight type:		**Tow bar type:**	
Charging cables:		**Fast charging cables:**	

TIRES

Position	Depth	Brand	Dimensions	Kind	Rims	Runflat
Front left	7 mm			Winter	Aluminum	?
Front right	7 mm			Winter	Aluminum	?
Rear left	7 mm			Winter	Aluminum	?
Rear right	7 mm			Winter	Aluminum	?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Rental	Damage type
2	Alloy rim FL	Scratches

Total: 1

ACCEPTABLE / NOT TO BE INVOICED

#	Rental	Damage type	Renta®	Repaired	Already invoiced
1	Bodywork	Teeth and scratches	✓	✗	✗
3	Wing RR	Scratches	✓	✗	✗

Total: 2

DAMAGE DETAILS

2 - Alloy rim FL - Scratch(es)




1 - Bodywork - Dent(s) and scratch(es) - Renta®














3 - Wing RR - Scratch(es) - Renta®




SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

12/08/2026 14:24

