



Mercedes A-Klasse (UKL): 2AKD466

Vinnumber:	W1K1770101V104730	Versionname:	A180d Business Solution 2.0d 116pk/cv 5p 8G-DCT
First Registrationdate:	22/04/2021	Fiscalpower:	
Expertise Mileage:	170486	Power Kw:	85
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

205/60/16/92 V				
Summer tyres:	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/60 R 16 92 V
Tyre size FR				205/60 R 16 92 V
Tyre size RL				205/60 R 16 96 V
Tyre size RR				205/60 R 16 96 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Interior, Dirty, Chemical cleaning





Bumper F, Scratch(es), Acceptable



Alloy rim FL polished, Chemical polution, Acceptable



Central pillar L, Dent(s), Acceptable



Alloy rim RL polished, Chemical polution, Acceptable



Luggage compartment cover, Broken, Replace



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Dent(s) and scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Acceptable



Door RR, Dent(s), Acceptable



Central pillar R, Dent(s), Acceptable



Alloy rim FR polished, Chemical polution, Acceptable



Wing FR, Dent(s), Acceptable



Kenteken	2AKD466
Merk Model	Mercedes A180d Business Solution 2.0d 116pk/cv 5p 8G-DCT
Brandstofsoort	Diesel
Datum deel1	4/22/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
6/2/26	164,924	accu	Vervangen
6/2/26	164,924	klein materiaal	
4/23/26	164,924	brandstof hoofdfilter	Vervangen
4/23/26	164,924	klein materiaal	
4/23/26	164,924	luchtfilter	Vervangen
4/23/26	164,924	mercedes assyst b	Uitvoeren
4/23/26	164,924	trekhaak	Controleren
8/14/25	139,314	klein materiaal	
8/14/25	139,314	mercedes assyst a	Uitvoeren
8/14/25	139,314	remvloeistof	Vervangen
8/14/25	139,314	versnellingsbakolie	Vervangen
11/26/24	116,800	klein materiaal	
11/26/24	116,800	mercedes assyst b	Uitvoeren
11/26/24	116,800	remblokken achter	Vervangen
11/26/24	116,800	remblokken vooraan	Vervangen
11/26/24	116,800	ruitenswisserrubber vooraan	Vervangen
11/26/24	116,800	trekhaak	Vervangen
12/18/23	83,627	brandstoffilter	Vervangen
12/18/23	83,627	klein materiaal	Uitvoeren
12/18/23	83,627	luchtfilter	Vervangen
12/18/23	83,627	mercedes assyst a	Uitvoeren
2/23/23	56,130	klein materiaal	Uitvoeren
2/23/23	56,130	mercedes assyst b	Uitvoeren
2/23/23	56,130	remschijven en blokken vooraan	Vervangen
2/23/23	56,130	remvloeistof	Vervangen
2/23/23	56,130	ruitenswisserrubber vooraan	Vervangen
2/23/23	56,130	trekhaak	Controleren
4/19/22	27,127	klein materiaal	Uitvoeren
4/19/22	27,127	mercedes assyst a	Uitvoeren