SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Bas Vaasen

2-FLP-540

2-FLP-540 · ST Line X 1.0i EcoBoost 155pk - 114kW - Mhev A7 -Clipper - leather seats · 4 November 2026 · Zaventem Brussel

Specifications

License Plate Number	2-FLP-540
Manufacturer	FORD
Model	Focus
Model Versions	ST Line X 1.0i EcoBoost 155pk - 114kW - Mhev A7 - Clipper - leather seats
Body Type	Station Wagon
Color	Black
Paint Type	Metallic
Production Year	2024
KW	114
Fuel Type	Gasoline

VIN	WF0PXXGCHPRG13362
Cylinder Capacity	999 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	11-06-2024
First Registration	11-06-2024
Odometer	69.713 Km
Numer Of Keys	2
Interior	Black – Leather
Number Headrests	5

Images































Accessories

ABS	Electric windows front
Airbags	Electrically adjustable exterior mirrors
Alloy wheels	Navigation system
ASR	Parking sensors
Audio System	Rear view camera
Automatic air conditioning	Roller cover / parcel shelf
Bluetooth car kit	Seat heating
Central door locking	Steering wheel multifunction
Centre armrest	Steeringwheel – Heated
Cruise control	Windscreen – Heated
Electric rear windows	

Condition

Condition exterior	Adequate	Last Maintenance	Unknown
Condition interior	Adequate	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Rear Left	3 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Front Right	4 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Rear Right	3 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Spare Tire Type	Compressor					

Damages




Damage Part	Damage Type	Repair Type	Acceptable
Other	small dents / small scratches	Panelbeating & Spotrepair	No





Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	Dent(s) & Scratch(es)	Panelbeating & Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	Dent(s) & Scratch(es)	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Right	Small scratch(es)	Acceptable	Yes







Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Spray	No





Damage Part	Damage Type	Notes	Repair Type	Acceptable
Alloys	Scratch(es)	RV - RA - LV	Rim repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Door-edge chipped	Acceptable	Yes




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Small scratch(es)	Acceptable	Yes




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Scratch(es)	Polish	No






Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Spray	No