


Vehicle details

VIN	VR3UKZKXZ LJ834131	Brand	PEUGEOT	Maintenance date	-
Licence Plate		Model	2008 GT EV 50kWh 136 5d	Maintenance mileage	-
Registration date	08/12/2020	Year	2020	Exterior Color	Blue Metallic
Odometer	103 558 km	Engine size	-	Interior Color	Black
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	24/04/2026	Inspection loc.	
-----------------	------------	-----------------	--



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Sliding roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Spare wheel kit	✓
Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✗

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 215/55/18 All seasons 4.5 mm



Pirelli 215/55/18 All seasons 4.5 mm




Pirelli 215/55/18 All seasons 3.5 mm

Pirelli 215/55/18 All seasons 3.5 mm


Exterior

2



Part	Door
Position	Front left
Damages	Improper repair
Severity	-
Repair mode	Repair

3



Part	Wing
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Repair

5



Part	Roof post A/B/C
Position	Left
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

6



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

7



Part	Bumper
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Repair

8



Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

9



Part	Door
Position	Front right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

10



Part	Wing
Position	Front right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

11



Part	Alloy wheel 18"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

12



Part	Bonnet
Position	-
Damages	Dent & Chips
Severity	-
Repair mode	Repair

13



Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

14



Part	Step plate
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

Interior damage

4



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

Others

1



Part	Wireless charger
Position	-
Damages	Missing
Severity	-
Repair mode	For info