

APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name: -
Make: AUDI
Model / version: A5 SPORTBACK
Vin: WAUZZZF58NA007457
Plate:
Mileage: 90956
SOH:
First registration: 15/11/2021
Color: Mythoszwart




ADDITIONAL INFORMATION





Category:
Transmission:
Interior color:
Metallic paint: ?
Type of lining:
Board computer reset: ?

DOCUMENTS

Certificate of conformity: ✓
Registration certificate: ✓
Registration certificate 2: ✓
Insurance certificate: ?
Maintenance book:
Number of keys: 2
Original key: ✓

PICTURES





VIN INFORMATION

Transmission séquentielle
Lettre repère (J)
Largeur avant 7,5
Diamètre arrière 17
Indice de vitesse avant Y
Largeur arrière 225
Freins avant à disques
Rétroviseur gauche chauffant
Sièges avant chauffants
Volant sport
Caméra avant

7 rapports
Diamètre avant 17
Largeur arrière 7,5
Hauteur avant 50
Indice de vitesse arrière Y
Climatisation réfrigérant 1234YF
Rétroviseur gauche à réglage électrique
Rétroviseur droit chauffant
Garnitures cuir et simili-cuir
Volant multifonction
Régulateur et limiteur de vitesse

Matière : alliage
Diamètre arrière 17
Diamètre avant 17
Hauteur arrière 50
Largeur avant 225
Métallisée vernissée
Rétroviseur droit à réglage électrique
Siège avant gauche chauffant
Volant cuir
Aide au stationnement arrière
Équipement Stop & Start

Affichage lecture des panneaux de signalisation
Airbag passager
Témoin d'oubli de ceinture arrière
réservoir supplémentaire SCR 24 L
dossiers ar séparés
transmission hybride M-HEV
roues av motrices (traction)

Carte mains libres
Airbag passager désactivable
Protection piéton
rétroviseur g avec miroir asphérique
norme anti-pollution Euro 6 AP
1968 CC 100 KW
FREINS AR 300X12

Appel de secours
Témoin d'oubli de ceinture avant depuis 10.21
rétroviseur d convexe
radio avec récepteur numérique
réservoir carburant 54 L
support plaque immat avant (grand)

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	✓	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	✓
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			Summer		?
Front right	5 mm			Summer		?
Rear left	5 mm			Summer		?
Rear right	5 mm			Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Bumper F	Grooved
3	Bumper R	Grooved
5	Door FL	Dent(s) and scratch(es)

Total: 3


ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
2	Bodywork	Dent(s) and scratch(es)	✓	✗	✗
4	Tailgate / Boot - Kofferklep gaat enkel open met sleutel p-controleren	No damage	✓	✗	✗


Total: 2

DAMAGES DETAILS

1 - Bumper F - Grooved





3 - Bumper R - Grooved



5 - Door FL - Dent(s) and scratch(es)



2 - Bodywork - Dent(s) and scratch(es) - Renta®



4 - Tailgate / Boot - Kofferklep gaat enkel open met sleutel p-controleren - No damage - Renta®



SIGNATURE

Expert
17/07/2026 08:40