



Mercedes C-Klasse (KKL): 2BHx468

Vinnumber:	W1K2062031F033266	Versionname:	C200d Break Business Line 2.0d 163pk/cv 5p 9G-Tronic
First Registrationdate:	2/12/2021	Fiscalpower:	
Expertise Mileage:	70150	Power Kw:	120
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	Service A +218 d		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/55/17/91 W			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/55 R 17 91 W
Tyre size FR				205/55 R 17 91 W
Tyre size RL				205/55 R 17 95 V
Tyre size RR				205/55 R 17 95 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				256
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Bumper moulding F, Scratch(es), Acceptable



Bumper F, Scratch(es), Acceptable




Alloy rim FL, Scratch(es), Repair and paint (complete)



Alloy rim RL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Acceptable



Bumper R, Bad repair, Repair and paint (complete)



Tailgate / Boot, Dent(s), Paintless dent repair



Wing RR, Bad repair, Repair and paint (complete)



Alloy rim RR, Scratch(es), Repair and paint (complete)




Alloy rim FR, Scratch(es), Repair and paint (complete)



Bodywork, Not original part, Remove lettering



Roof, Dent(s), Repair and paint (complete)



Kenteken	2BHX468
Merk Model	Mercedes C200d Break Business Line 2.0d 163pk/cv 5p 9G-Tronic
Brandstofsoort	Diesel
Datum deel1	12/2/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
2/6/26	57,051	batterij	Vervangen
2/6/26	57,051	brandstoffilter	Vervangen
2/6/26	57,051	klein materiaal	
2/6/26	57,051	luchtfilter	Vervangen
2/6/26	57,051	mercedes assyst b	Uitvoeren
2/6/26	57,051	remvloeistof	Vervangen
2/6/26	57,051	ruitenswisserrubber vooraan	Vervangen
2/6/26	57,051	stoffilter (motor compartiment)	Vervangen
8/20/25	50,330	controle niveaus	Uitvoeren
1/31/25	43,243	klein materiaal	
1/31/25	43,243	mercedes assyst a	Uitvoeren
1/31/25	43,243	stoffilter (motor compartiment)	Vervangen
2/8/24	32,340	klein materiaal	Uitvoeren
2/8/24	32,340	mercedes assyst b	Uitvoeren
2/8/24	32,340	remvloeistof	Vervangen
2/8/24	32,340	ruitenswisserrubber achter	Vervangen
2/8/24	32,340	ruitenswisserrubber vooraan	Vervangen
2/8/24	32,340	stoffilter (motor compartiment)	Vervangen
2/7/23	22,859	klein materiaal	Uitvoeren
2/7/23	22,859	mercedes assyst a	Uitvoeren
2/7/23	22,859	stoffilter (motor compartiment)	Vervangen