



Expertise

Protocol number: 46435829  
Order No. / Reference: 26707134  
Inspection date: 10 Jul 2026

Manufacturer: Ford

Model: Mondeo Turnier 2.0 EcoBlue Aut. Titanium

VIN: WF0FXXWPCFNS68456



| Vehicle details                               |                      |
|-----------------------------------------------|----------------------|
| Manufacturer / Type / Model / Equipment       |                      |
| Ford Mondeo Turnier 2.0 EcoBlue Aut. Titanium |                      |
| Vehicle Identification number                 | WF0FXXWPCFNS68456    |
| Mileage (Read)                                | 142,763 km           |
| First registration                            | 27 Apr 2022          |
| Number of holders                             | 1                    |
| Next periodical technical inspection          | 04/2027              |
| (Report not on hand)                          |                      |
| Power / Engine displacement                   | 110 kw / 1,995 ccm   |
| Fuel type / Cylinder                          | Diesel / 4           |
| Gearbox / Number of gears                     | Automatic / 8        |
| Type of drive                                 | Front drive          |
| Type of vehicle                               | Station wagon        |
| Colour / colour code                          | Agate Black Metallic |
| Doors / Seats                                 | 5 / 5                |
| Upholstery type                               | Cloth                |
| Colour of upholstery                          | Anthracite           |



## Vehicle details

|                                                  |                              |                                |                                                            |
|--------------------------------------------------|------------------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | digital proof / complete     | <b>Next maintenance in</b>     | 64 %                                                       |
| <b>Last service on / at</b>                      | 05/2026 at 139,250 km        |                                |                                                            |
| <b>Key is / should be</b>                        | 2 / 2                        | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                                  |                              | <b>Letter No.</b>              | GK805338                                                   |
| <b>Previous damage / Accident</b>                | Detectable                   | <b>Repainting</b>              | Detectable                                                 |
| <b>Inspection conditions</b>                     | sufficient                   | <b>Lifting equipment / pit</b> | yes                                                        |
| <b>Test drive</b>                                | Not performed                | <b>Engine function test</b>    | Performed                                                  |
| <b>Manufacturer key number/ type code number</b> | 8566 / BJB 00110             |                                |                                                            |
| <b>Emission standard</b>                         | EURO6;WLTP;AP;PI/CI; M, N1 I | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                    | 2,330 kg                     | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size      | Type of tyre                | Manufacturer | Tread depth |
|----|----------------|-----------------------------|--------------|-------------|
| 1) | 215/55 R17 98W | Summer tyres on Light alloy | Goodyear     | 3mm / 3mm   |
| 2) | 215/55 R17 98W | Summer tyres on Light alloy | Goodyear     | 5mm / 5mm   |

### Additional tyres

| #  | Tyre size      | Type of tyre                | Manufacturer | Tread depth |
|----|----------------|-----------------------------|--------------|-------------|
| 1) | 215/60 R16 99H | Winter tyres on Light alloy | Goodyear     | 7mm / 7mm   |
| 2) | 215/60 R16 99H | Winter tyres on Light alloy | Goodyear     | 7mm / 7mm   |

**Legend:** Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

## Equipment

### Standard equipment

- Activated carbon filter
- Anti-lock braking system (ABS) with electronic brake force distribution (EBD)
- Attachment points for safety partition grilles
- Tires: 7 J x 17 alloy wheels (4) with 215/55 R 17 tires (in 10x2-spoke design in luster nickel premium paint finish)
- Hill start assist
- Chrome decor
- Roof rails, aluminum look
- Tachometer
- Electronic Shifter
- Driver information system - 25.4 cm color display (digital/analog)
- Electric windows front and rear
- Electronic parking brake
- Ford Power Start function
- Heated windshield
- Luggage compartment cover
- Cruise control system with intelligent speed limiter
- Back window, heater
- Interior lighting with delay circuit
- Intelligent security system
- Electric child safety lock
- Rear headrests (3), height adjustable
- LED design daytime running lights in the fog lights
- Adjustable steering column
- Front center console with padded armrests
- Navigation: Ford Navigation including Ford SYNC 3 with AppLink, 8" touchscreen (20.3 cm screen) with DAB/DAB+
- Front and rear parking pilot system
- LED taillights
- Windscreen wipers with rain sensor
- Headlight assistant with day/night sensor
- Side skirts painted in car color
- Seats: Driver and passenger seats, 4-way manually adjustable
- Seats: Sports seats with fabric upholstery
- Start-stop system
- 12-volt socket in the front interior
- Daytime running light
- Traffic sign recognition system
- Warning system for unfastened seat belts in the front and second row of seats
- Cigarette lighter
- Ambient lighting in the front, including door storage compartment, front door handle and footwell lighting.
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated
- Tires: Tire repair kit
- Tires: Tire pressure monitoring system (TPMS)
- Third brake light
- Headliner, light
- Diesel particulate filter (DPF)
- Front door sill trim
- Electronic Safety and Stability Program (ESP)
- Lane keeping assist including lane keeping assist and driver fatigue warning
- High Beam Assist
- Ford Easy Fuel
- FordPass Connect including eCall, live traffic information and Wi-Fi hotspot
- Luggage compartment lighting
- Transmission: 8-speed automatic transmission
- Rear window wiper
- Interior mirror automatically dimming
- Isofix bracket
- Air conditioning with automatic temperature control
- Front headrests, 4-way height and tilt adjustable
- Steering wheel: Multifunction leather steering wheel
- Reading lights front and rear
- MyKey key system (individually programmable second key)
- Fog light
- Emergency brake light
- Pre-Collision Assist
- Rear seat backrest, foldable, 60:40 split
- Headlight dipped beam with switch-off delay including "greeting function"
- Electromechanical speed-dependent power steering
- Seats: Map pocket on the back of the front passenger seat
- Seats: Map pocket on the driver's seat backrest
- Seats: Front seats can be heated individually and variably.
- 12-volt power outlet in the luggage compartment
- Front bumper painted in body color
- Carpet floor mats front and rear
- Lashing eyes in the luggage compartment floor
- Immobiliser
- Central locking



## Extra equipment

- Detachable towbar (ESP trailer stabilization - continuous power supply - switched power supply - hill start assist)
- Package: Winter (Heated windscreen - Heated leather steering wheel - 230-volt socket in center console (not in conjunction with hybrid engine) - Individually and variably heated front seats - Variably heated rear bench seat)
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Safety partition net behind the 2nd row of seats for the luggage compartment
- Seats: Ford ergonomic seat (driver and front passenger seat adjustable in 18 ways: - length, height and tilt of the seat - extendable thigh support - adjustable backrest - lumbar support electrically adjustable in 4 ways - fabric upholstery)
- Paint finish: Metallic
- Package: Business 1 (Exterior mirrors, electrically adjustable and heated, additionally electrically folding and with ambient lighting - Park Assist with parallel and perpendicular parking function incl. Park Pilot system - Ford Navigation system incl. Ford SYNC 3 with AppLink, 8" touchscreen (20.3 cm) with DAB/DAB+ - Audible and visual route guidance, Live Traffic in conjunction with FordPass - 8 speakers - Steering wheel remote control - Bluetooth hands-free system and audio streaming - 2 USB ports - Voice control for audio and telephone - LED design daytime running lights - Rearview camera)

## Brief expert findings

|                      |                                                                                                                                                                              |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.    |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle.                     |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                        |
| Engine function test | An engine test run was performed.                                                                                                                                            |

## Value reducing factors

| No. | Component group             | Description                                                                                              |
|-----|-----------------------------|----------------------------------------------------------------------------------------------------------|
| 1   | Seat - front                | Seat cover - right side (Sitze) - Soiled - Clean                                                         |
| 2   | Equipment                   | Vehicle key - Empty - Replace                                                                            |
| 3   | Headlight                   | Headlight - right side (Leuchtmittel H7) - Non-operational - Perform diagnosis                           |
| 4   | Side panel - rear left side | Sill - Scratch(es) - Smart repair                                                                        |
| 5   | Steering system             | Steering wheel sheath - Scratched - Smart repair                                                         |
| 6   | Boot lid / rear door        | Boot lid (Unterteil) - Scratch(es) - Paint                                                               |
| 7   | Door - rear left side       | Door - Dent / paintcoat damage - Repair and paint                                                        |
| 8   | Bonnet                      | Bonnet - Scratch(es) - Paint                                                                             |
| 9   | Front bumper                | Front bumper - Scratched - Repair and paint                                                              |
| 10  | Rear bumper                 | Rear bumper (Incl. Zierleiste schwarz erneuern+AHK prüfen) - Scratched - repair according to calculation |

## Wear and tear

| No. | Component group | Description                            |
|-----|-----------------|----------------------------------------|
| 1   | 2nd wheel set   | 1 alloy rim - Scratched - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.



## Missing parts

### Description

Rear of vehicle - Key trailer hitch (2x)

Wheel / tyres - Wheel cover set - complete (Nabendeckel)

Equipment - Tirefit complete

## Previous damages

| No. | Previous damage                                           | Extent of damage (Net) |
|-----|-----------------------------------------------------------|------------------------|
| 1   | Side right, Provided by user / customer, from 5 Sept 2025 | 3.392,75 €             |

## Repainting

### No. Repainting

1 Mudguard - right side, Door - rear right side, Door - front right side, Professionally carried out

## Paint coat thickness measurement

|                         |        |                        |        |
|-------------------------|--------|------------------------|--------|
| Mudguard - right side   | 168 µm | Door - rear right side | 188 µm |
| Door - front right side | 202 µm |                        |        |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.



## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

## Comments

Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkter Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung, Mehrkosten und somit Abweichung der für die Stoßstange ausgewiesenen Reparaturkosten nicht ausgeschlossen werden.



ALPHABET



Figure 1: Diagonal front (left)

ALPHABET



Figure 2: Diagonal front (right)

ALPHABET



Figure 3: Diagonal rear (left)

ALPHABET



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear





Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres






Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.





Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.






Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Damage 1: Seat - front: Seat cover - right side (Sitze) - Soiled - Clean



Damage 1: Seat - front: Seat cover - right side (Sitze) - Soiled - Clean





**Damage 1:** Seat - front: Seat cover - right side (Sitze) - Soiled - Clean




**Damage 1:** Seat - front: Seat cover - right side (Sitze) - Soiled - Clean



**Damage 2:** Equipment: Vehicle key - Empty - Replace



**Damage 3:** Headlight: Headlight - right side (Leuchtmittel H7) - Non-operational - Perform diagnosis



**Damage 3:** Headlight: Headlight - right side (Leuchtmittel H7) - Non-operational - Perform diagnosis



**Damage 3:** Headlight: Headlight - right side (Leuchtmittel H7) - Non-operational - Perform diagnosis





**Damage 4:** Side panel - rear left side: Sill - Scratch(es) - Smart repair




**Damage 4:** Side panel - rear left side: Sill - Scratch(es) - Smart repair



**Damage 4:** Side panel - rear left side: Sill - Scratch(es) - Smart repair



**Damage 5:** Steering system: Steering wheel sheath - Scratched - Smart repair



**Damage 5:** Steering system: Steering wheel sheath - Scratched - Smart repair



**Damage 5:** Steering system: Steering wheel sheath - Scratched - Smart repair






**Damage 5:** Steering system: Steering wheel sheath - Scratched - Smart repair



**Damage 5:** Steering system: Steering wheel sheath - Scratched - Smart repair



**Damage 6:** Boot lid / rear door: Boot lid (Unterteil) - Scratch(es) - Paint



**Damage 6:** Boot lid / rear door: Boot lid (Unterteil) - Scratch(es) - Paint



**Damage 6:** Boot lid / rear door: Boot lid (Unterteil) - Scratch(es) - Paint



**Damage 6:** Boot lid / rear door: Boot lid (Unterteil) - Scratch(es) - Paint





**Damage 7:** Door - rear left side: Door - Dent / paintcoat damage - Repair and paint




**Damage 7:** Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



**Damage 7:** Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



**Damage 7:** Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



**Damage 7:** Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



**Damage 8:** Bonnet: Bonnet - Scratch(es) - Paint






**Damage 8:** Bonnet: Bonnet - Scratch(es) - Paint



**Damage 9:** Front bumper: Front bumper - Scratched - Repair and paint



**Damage 9:** Front bumper: Front bumper - Scratched - Repair and paint



**Damage 9:** Front bumper: Front bumper - Scratched - Repair and paint



**Damage 9:** Front bumper: Front bumper - Scratched - Repair and paint



**Damage 9:** Front bumper: Front bumper - Scratched - Repair and paint





**Damage 10:** Rear bumper: Rear bumper (Incl. Zierleiste schwarz erneuern+AHK prüfen) - Scratched - repair according to calculation




**Damage 10:** Rear bumper: Rear bumper (Incl. Zierleiste schwarz erneuern+AHK prüfen) - Scratched - repair according to calculation



**Damage 10:** Rear bumper: Rear bumper (Incl. Zierleiste schwarz erneuern+AHK prüfen) - Scratched - repair according to calculation



**Damage 10:** Rear bumper: Rear bumper (Incl. Zierleiste schwarz erneuern+AHK prüfen) - Scratched - repair according to calculation



**Damage 10:** Rear bumper: Rear bumper (Incl. Zierleiste schwarz erneuern+AHK prüfen) - Scratched - repair according to calculation



**Damage 10:** Rear bumper: Rear bumper (Incl. Zierleiste schwarz erneuern+AHK prüfen) - Scratched - repair according to calculation





**Wear and tear 1:** 2nd wheel set: 1 alloy rim - Scratched - No deduction



**Wear and tear 1:** 2nd wheel set: 1 alloy rim - Scratched - No deduction



**Missing part 1:** Rear of vehicle: Key trailer hitch (2x) - Missing - Replace



**Missing part 2:** Wheel / tyres: Wheel cover set - complete (Nabendeckel)  
- Missing - Replace



**Missing part 2:** Wheel / tyres: Wheel cover set - complete (Nabendeckel)  
- Missing - Replace



**Missing part 2:** Wheel / tyres: Wheel cover set - complete (Nabendeckel)  
- Missing - Replace



**Missing part 2:** Wheel / tyres: Wheel cover set - complete (Nabendeckel)  
- Missing - Replace



**Missing part 3:** Equipment: Tirefit complete - Missing - Replace



**Mudguard - right side:** 168 µm



**Door - rear right side:** 188 µm



**Door - front right side:** 202 µm





# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0FXXWPCFNS68456  
Hersteller / Modell: FORD FORD Mondeo Turnier 2.0 EcoBlue Aut. Titanium

| Datum      | KM-Stand | Beschreibung                                                                                                                                                                                                                     |
|------------|----------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 06.05.2026 | 139.250  | Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges |
| 05.09.2025 | 115.115  | Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                                                            |
| 29.04.2025 | 101.007  | AU                                                                                                                                                                                                                               |
| 10.12.2024 | 85.264   | Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                                                                                                         |
| 29.04.2024 | 59.400   | Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/ Eigendiagnose; Wartung Sonstiges                                         |
| 14.06.2023 | 30.152   | Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                                                                                                         |