




PEUGEOT 308 3

|                          |                   |
|--------------------------|-------------------|
| -                        |                   |
| VIN                      | VR3F3DGXTPY655150 |
| Première immatriculation | 27/11/2023        |

DÉTAILS DE L'INSPECTION

|                      |                     |                      |  |
|----------------------|---------------------|----------------------|--|
| Date de l'inspection | 25/02/2026 15:41:07 | Adresse d'inspection |  |
|----------------------|---------------------|----------------------|--|

INFORMATIONS SUR LE VÉHICULE

|                          |                      |                         |                      |
|--------------------------|----------------------|-------------------------|----------------------|
| VIN                      | VR3F3DGXTPY655150    | Transmission            | Avant                |
| Type de carrosserie      | Berline              | Nbre sièges             | 5                    |
| Nbre portes              | 5                    | Nombre appuis-têtes     | 5                    |
| Première immatriculation | 27/11/2023           | Couleur intérieur       | Noir                 |
| Type de carburant        | Hybride rechargeable | Couleur carrosserie     | Gris                 |
| Marque                   | PEUGEOT              | Catégorie               | Vehicule particulier |
| Modèle                   | 308 3                | Couleur tableau de bord | Noir                 |
| Boîte de vitesses        | Automatique          |                         |                      |

DOCUMENTS ET CLÉS

|                         |     |                                       |          |
|-------------------------|-----|---------------------------------------|----------|
| Carnet d'entretien      | Oui | Manuel d'utilisation                  | Oui      |
| Nbre clés total         | 1   | Certificat immatriculation (original) | Original |
| Nbre clés télécommandes | 1   | Certificat immatriculation (original) | Oui      |

OPTIONS

|                    |           |
|--------------------|-----------|
| Nature de peinture | Metallisé |
|--------------------|-----------|

DAMAGES

Interior



1 | Remote ignition key (no insert)

|             |                           |
|-------------|---------------------------|
| Damage type | Missing                   |
| Repair mode | Repair/replace (lump sum) |



13 | Charging cable (normal)

|             |         |
|-------------|---------|
| Damage type | Missing |
| Repair mode | Replace |

Exterior



2 | Alloy rim FL bitone/polychrome

|             |                           |
|-------------|---------------------------|
| Damage type | Scratch(es)               |
| Repair mode | Repair/replace (lump sum) |





3 | Tyre FL

|             |         |
|-------------|---------|
| Damage type | Tear    |
| Repair mode | Replace |



4 | Alloy rim RL bitone/polychrome

|             |                           |
|-------------|---------------------------|
| Damage type | Scratch(es)               |
| Repair mode | Repair/replace (lump sum) |



5 | Alloy rim RR bitone/polychrome

|             |                           |
|-------------|---------------------------|
| Damage type | Scratch(es)               |
| Repair mode | Repair/replace (lump sum) |





6 | Alloy rim FR bitone/polychrome

|             |                           |
|-------------|---------------------------|
| Damage type | Scratch(es)               |
| Repair mode | Repair/replace (lump sum) |



7 | Tyre FR

|             |         |
|-------------|---------|
| Damage type | Tear    |
| Repair mode | Replace |



8 | Roof pillar L

|             |                             |
|-------------|-----------------------------|
| Damage type | Dent(s)                     |
| Repair mode | Repair and paint (complete) |





9 | Bumper F

|             |             |
|-------------|-------------|
| Damage type | Scratch(es) |
| Repair mode | Paint       |




10 | Outer sill R

|             |                             |
|-------------|-----------------------------|
| Damage type | Dent(s) and scratch(es)     |
| Repair mode | Repair and paint (complete) |



11 | Wing FR

|             |             |
|-------------|-------------|
| Damage type | Scratch(es) |
| Repair mode | Paint       |



12 | Roof pillar R

|             |                             |
|-------------|-----------------------------|
| Damage type | Dent(s)                     |
| Repair mode | Repair and paint (complete) |



14 | Bumper R

|             |             |
|-------------|-------------|
| Damage type | Scratch(es) |
| Repair mode | Polish      |



15 | Roof

|             |                             |
|-------------|-----------------------------|
| Damage type | Dent(s)                     |
| Repair mode | Repair and paint (complete) |



## Commercial photos

